



Your Ref: 22/22/22/VC05/026384

Date: 09th Dec 2024

Our Ref: CS1/LPC24110481/Eqh3e2

M/s Lonpac Insurance Bhd

300 Beach Road
#17-04/07 The Concourse
Singapore 199555
(The Motor Claims Department)

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: XE 6167C
INSURED VEHICLE: YN 8868R
ACCIDENT DATE: 05/10/2022**

We thank you for your instruction on 22/11/2024.

We acknowledge receipt of the following documents:-

- a) Singapore Accident Statement of Vehicles XE 6167C, YN 8868R, GBH 5627T and XE 5812E.
- b) Police Report of Vehicles XE 6167C, YN 8868R and GBH 5627T.
- c) Colour damaged vehicle photographs of XE 6167C.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

| | |
|----------------------|------------------------------|
| Registration Number | : XE 6167C |
| Make & Model | : Hino FS1EKND 28 TON 6X4 MT |
| Year of Registration | : 2021 |
| Chassis Number | : JHDFS1EKNXXX10108 |
| Engine Capacity | : 12913 cc |

2. We recommend that the repairs of the entire damage require about 20 (Twenty) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.