



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

Ubi Customer Service Centre

330 Ubi Road 3, Singapore 408650 Tel: (65) 68661666



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Cycle & Carriage Kia Pte Ltd 239 Alexandra Road Singapore 159930 Contact No	Cust No/Name	/Cycle & Carriage Kia Pte Ltd
	Reg No/Reg Date	SNH6075L / 24/08/2021
	Date In/Mileage	21/11/2024/ 21121
	Chassis No	KNAF5416MN5115867
	Engine No	G4FGMH707927
	Make/Model	KIA/CERATO 1.6 A GT LINE H439 PE
Colour/Trim	CR5 RUNWAY RED / WK SATURN BLACK	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00080	Cash	21/11/2024/ 17:48	REN	979 / Renemer Ramirez Bag	36950

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
Z TEXT ACCIDENT ON 21/11/2024 ALONG TAMPINES AVENUE 10 OWNER CLAIMING THIRD PARTY REQUIRED REPLACEMENT VEHICLE TP#: SNH8552M TP INS: ECICS				
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON KDS AND CLEAR TROUBLE CODE				280.00
A 90000001 TO CHECK WIRING AND ELECTRICAL SYSTEM				100.00
E PNT88000 TO TRANSFER TRUNK LID COMPONENTS & MECHANISM				640.00
E PNT88000 TO REMOVE & RE-INSTALL FLOOR BOARDS, CARPETS & TRIMS TO FACILITATE REPAIR ON REAR ACCIDENT AFFECTED AREAS				640.00
E PNT88000 TO REPLACE LOGO, EMBLEM, TRUNK LID, UPR & LWR REAR BUMPER, CLIPS, SIDE BRACKETS, LH/RH T/SIGNAL LAMP & COVER, EXTN WIRING, ANTENNA, BEAM & BRACKETS, LH/RH STAY, LH UNDER COVER, ETC -TO REPAIR REAR END PANEL STRAIGHTEN, REFORM, ALIGN ON REAR ACCIDENT AFFECTED AREAS				2560.00
E PNT98000 SPRAY PAINT ON REAR ACCIDENT AFFECTED AREAS (TRUNK LID, UPR REAR BUMPER, REAR END PANEL)				2200.00
E PNT88000 TO CHECK, TEST & REFIT REVERSE SENSOR				100.00
M SUNDRY TO APPLY BODY SEALANT ON NEW PANELS (Rear)				200.00
M SUNDRY TO APPLY ANTI-CORROSION ON AFFECTED AREAS (Rear)				200.00
M SUNDRY SUNDRIES				50.00
M EMBLEM-KIA	1.00	38.00	00.00	38.00
M EMBLEM-CERATO	1.00	28.00	00.00	28.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

Ubi Customer Service Centre

330 Ubi Road 3, Singapore 408650 Tel: (65) 68661666



Movement that inspires

ESTIMATE

Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Cycle & Carriage Kia Pte Ltd 239 Alexandra Road Singapore 159930 Contact No	Cust No/Name	/Cycle & Carriage Kia Pte Ltd
	Reg No/Reg Date	SNH6075L / 24/08/2021
	Date In/Mileage	21/11/2024/ 21121
	Chassis No	KNAF5416MN5115867
	Engine No	G4FGMH707927
	Make/Model	KIA/CERATO 1.6 A GT LINE H439 PE
Colour/Trim	CR5 RUNWAY RED / WK SATURN BLACK	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00080	Cash	21/11/2024/ 17:48	REN	979 / Renemer Ramirez Bag	36950

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M EMBLEM-GT LINE / RC	1.00	45.00	00.00	45.00
M PANEL ASSY-TRUNK LID / RC	1.00	1810.00	00.00	1810.00
M COVER-RR BUMPER / RC	1.00	749.00	00.00	749.00
M COVER-RR BUMPER LWR / RC	1.00	232.00	00.00	232.00
M CLIP-BUMPER / RC	10.00	1.00	00.00	10.00
M BRACKET ASSY-RR BPR SIDE UPR,LH / RC	1.00	31.00	00.00	31.00
M BRACKET-ASSY RR BPR SIDE UPR,RH / RC	1.00	26.00	00.00	26.00
M COVER-RR BUMPER FOG LAMP,LH / X	1.00	39.00	00.00	39.00
M COVER-RR BUMPER FOG LAMP,RH / X	1.00	39.00	00.00	39.00
M LAMP ASSY-SIDE T/SIGNAL,LH / X	1.00	201.00	00.00	201.00
M LAMP ASSY-SIDE T/SIGNAL,RH / X	1.00	201.00	00.00	201.00
M ULTRASONIC SENSOR ASSY-BWS / ?	1.00	163.00	00.00	652.00
M EXTN WIRING ASSY-BWS / ?	1.00	207.00	00.00	207.00
M ANTENNA ASSY-SMARTKEY / ?	1.00	46.00	00.00	46.00
M BRACKET-RR BPR UPR MTG / ?	2.00	42.00	00.00	84.00
M BRACKET-RR BEAM LWR,CTR / ?	1.00	6.00	00.00	6.00
M BRACKET-RR BEAM LWR MTG / ?	2.00	7.00	00.00	14.00
M BEAM-RR BUMPER / ?	1.00	318.00	00.00	318.00
M STAY-RR BUMPER LH / ?	1.00	65.00	00.00	65.00
M STAY-RR BUMPER RH / ?	1.00	65.00	00.00	65.00
M COVER-RR BUMPER UNDER,LH / X	1.00	33.00	00.00	33.00

STEVE CLKK
 26/11/24, 10:30am
 W K
 PIP
 by Bel my

Confirm & accepted by

4 days

	Nett	11,909.00
9% GST on	11909.00	1071.81
	Total Payable	12,980.81

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

This is a computer generated document, no signature is required.
 The above estimate is based on our initial inspection and does not include any work that has commenced. Occasionally worn or damaged parts are discovered however, should this occur, we would advise you. Please be informed that a deposit of the work. Payment for this may be made in cash, credit card or the windscreen in the event of inadvertent breakage in the course of renewing the windscreen.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of First Submission	21/11/2024 16:16 (SGT)
Reported by	Actual Driver
Date of Accident	21/11/2024 08:45 (SGT)
Exact Location of Accident	Tampines Ave 10, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SNH6075L
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	CYCLE & CARRIAGE KIA PTE LTD
Company Reg No	1XXXXX410K
Email Address	juliana.lim@cyclecarriage.com.sg
Mobile Phone No	(Phone) +65-64278834
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Kia
Model	Cerato
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1591
Vehicle Fuel	Petrol
First Registration Date	24/08/2021
Chassis no	KNAF5416MN5115867
Effective Date/Time of Ownership	24/08/2021 00:00 (SGT)

INSURANCE COMPANY

Name of Insurance Company	MSIG Insurance (Singapore) Pte. Ltd.
Policy Number / Cover Note Number	B 400002678 MCY

DRIVER

Name of Driver	CHUA HONG MIN
IC No	SXXXX634C
Date Of Birth	02/03/1993
Occupation	Indoor
Driving Pass Date	18/10/2018
Driving License Pass Class	3
Driving License Validity	Valid
Driving experience	6 YEARS AND 1 MONTH
Gender	Female
Mobile Number	(Phone) +65-82336508
Alt. Phone Number	-
Email Address	bertha.chua@cyclecarriage.com.sg
Address	BLK 625B TAMPINES STREET 61 #15-656 SINGAPORE
Address complement	-
Postcode	522625
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Employee
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO THE ATTACHMENT

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SNH8552M
Vehicle Manufacturer	BMW

Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	KEVIN
Contact Number	(Phone) +65-98318340
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


21/11/24




Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



VEHICLE A = SNH6075L

VEHICLE B = SNH8552M

Describe Circumstances of the Accident

I was waited along Tampines Ave 10 for the traffic light to turn green. Suddenly, before moving off as the traffic light turned green, I felt a huge impact from the back and saw Car B hit onto the rear of my car.

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

 21/11/21

