



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL			Ref:	CS/SMO24110484/Avp3m4 (N)
50 RAFFLES PLACE #03-03			Date:	18/02/2025
SINGAPORE LAND TOWERSINGAPORE 048623			Code:	SMO
ATTN: THELMA				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBJ 5495X	Veh. Inspected	SGT 718A	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2403775/THE	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	22/11/2024	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI PDE I30N	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	TMAHC51ALKJ007097	Colour	RED	
Odometer	58811 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/40R18	MICHELIN	6 mm	
L/H Front Tyre	225/40R18	MICHELIN	6 mm	
R/H Rear Tyre	225/40R16	MICHELIN	6 mm	
L/H Rear Tyre	225/40R16	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	20/11/2024	Inspection Date	19/12/2024	
Survey held at	ELITE AUTOMOTIVE 280 WOODLANDS INDUSTRIAL PARK E5 #01-17 HARVEST@WOODLANDS SINGAPORE 757322			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	