

ASSIGNMENT

Front: _____ Date: _____

Estim: _____

OD / TP RES / OD RES / EVA / INV / MV

To in _____ Vehicle No: _____

at _____

of _____

Insured: _____

Policy No: _____

Claim's No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: Tleveh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repair: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SGT 718A Yr Regn: 2019 April

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai 130 C.D. 1998

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: 58811 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: TMAHCSIALKJ007097

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/40 R16

R: 225/40 R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: _____ Rear: _____

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 19/12/24

Survey held at Elite Automobile

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP Surp</u>
	<u>COE Expiry</u>
	<u>Estimate given during : Yes (✓)</u>
	<u>1st Survey : No ()</u>
	<u>MV : 68K</u>
	<u>PV : 43.5K</u>
	<u>Nett : 24.5K</u>
	<u>134H</u>

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

1) _____
Date/Time, File Return to?

☐ : Final Report

Resurvey No. of Trip: _____

2) _____

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Inve (\$

Survey Fee: _____

Transportation: _____

3 + RS. \$1

Photos

Others

Report Format: _____

ELITE AUTOMOTIVE PTE LTD

280 Woodlands Industrial Park E5, #01-17,

Harvest @ Woodlands Singapore 757322

Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : SGT718A

Vehicle Model : HYUNDAI PDE130N

Chassis Number : TMAHC51ALKJ007097

Estimated Repair Cost

S/N	Parts Description	Qty	List Price
1	BONNET <i>new</i>	1	\$ 1857.00 +
2	FRONT BUMPER <i>del'd</i>	1	\$ 678.00 ✓
3	FRONT BUMPER CLIPS <i>m</i>	10	\$ 50.00 <i>30</i>
4	FRONT BUMPER RETAINER (RHS) <i>del'd</i>	1	\$ 120.00 <i>60</i>
5	FRONT BUMPER LOWER LIP <i>at</i>	1	\$ 188.00 ✓
6	FRONT BUMPER TOP RUBBERSTRIP <i>new</i>	1	\$ 110.00 +
7	FRONT RHS FOG LAMP <i>del'd</i>	1	\$ 643.00 <i>455</i>
8	FRONT RHS FOG LAMP COVER <i>del'd</i>	1	\$ 106.00 ✓
9	RHS HEADLAMP <i>at</i>	1	\$ 3018.00 ✓
10	FRONT RHS FENDER <i>Rep's</i>	1	\$ 2071.00 +
11	FRONT RHS SPLASH SHIELD <i>for new</i>	1	\$ 90.00 +
12	FRONT RHS SPLASH SHIELD CLIPS <i>new new</i>	10	\$ 50.00 +
13	FRONT RHS DOOR <i>new</i>	1	\$ 2138.00 ✓
14	FRONT BUMPER SENSOR <i>new</i>	1	\$ 169.00 +
			\$ 11288.00
Discount Less 20%			\$ 2257.60
List Prices Total			\$ 9,030.40

ELITE AUTOMOTIVE PTE LTD

280 Woodlands Industrial Park E5, #01-17,

Harvest @ Woodlands Singapore 757322

Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : SGT718A

Vehicle Model : HYUNDAI PDE130N

Chassis Number : TMAHC51ALKJ007097

S/N	Labour Descriptions	Charges
1	LABOUR CHARGES TO REMOVE & INSTALL FRONT RHS END ATTACHMENTS & FITTINGS TO ENABLE REPAIRS; TO CUT & WELD WHERE NECESSARY; TO REPLACE DAMAGED PARTS AS LISTED ABOVE	\$ 1500.00 400
2	TO SPRAY PAINTING ON: BONNET, FRONT BUMPER, FRONT RHS DOOR, FRONT RHS FENDER, FRONT BUMPER LOWER LIP	\$ 1200.00 800
3	TO REMOVE & TRANSFER RHS & FRONT DOOR TRIM BOARD, DOOR SCREEN, POWER WINDOW & ELECTRICAL WIRINGS & SERVICEABLE FITTINGS TO NEW DOOR & TEST FUNCTION.	\$ 400.00 +
4	TO CHECK ELECTRICAL WIRINGS & HEADLIGHTS FUNCTIONS	\$ 150.00 30
5	TO CHECK DIAGNOSE & REMOVE FAULT CODES AFTER ACCIDENT REPAIRS.	\$ 280.00 +
6	TO REMOVE & REPLACE FRONT BUMPER SENSORS & TEST FUNCTION.	\$ 150.00 50

\$ 3680.00

Parts & Labour Total

\$ 12710.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj

1/5 19/12/24

04 Days,

96893735