



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

ATTN: RAJESWARY

Ref: CS/INC24110486/Uqh3e2(N)

Date: 07/01/2025

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SNM 2088A	Veh. Inspected	SMJ 7285S
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1305100-002	Excess (\$)	0.00
Assign From	RAJESWARY	Assign Date	22/11/2024

2. Vehicle Particulars & Condition

Make & Model	MITSUBISHI ATTRAGE 1.2 (A)	c.c	1193
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	MMBSTA13AKH001155	Colour	RED
Odometer	32500 KM	Steering	AFFECTED
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/55 R15	AUTOGREEN	6 mm
L/H Front Tyre	185/55 R15	AUTOGREEN	6 mm
R/H Rear Tyre	185/55 R15	AUTOGREEN	6 mm
L/H Rear Tyre	185/55 R15	AUTOGREEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR, FRONT AND N/S FRONT PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	19/11/2024	Inspect Date / Time	25/11/2024 (09:34 AM)
Survey held at	BLUWEL AUTOMOTIVE SERVICE PL BLK 1 KAKI BUKIT AVE 6 #01-28/53/55/56 (MAIN OFFICE) SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	16 Working Days
-------------------------------------	-----------------