



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS AUTO & GENERAL INSURANCE (S) PL	Ref:	CS/AGI24060293/Uqh3
(BUDGET DIRECT INSURANCE)	Date:	26/08/2024
190 CLEMENCEAU AVENUE #03-01		
SINGAPORE SHOPPING CENTRE SINGAPORE 239924	Code:	AGI

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKW 906K	Veh. Inspected	SMH 8365Z
Policy No.	-	Coverage	0
Claim No.	C10030201/KR	Excess	\$0.00
Assign From	MICHAEL	Assign Date	27/06/2024

### 2. Vehicle Details

Make & Model	VOLKSWAGEN GOLF GTI 2.0 A	C.C	1984
Engine No.	LTA1201076	Year of Reg.	14/02/2007
Chassis No.	WVWZZZ1KZ7W104537	Colour	BLUE
Odometer	394355 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	225/40R18	PIRELLI	6
L/H Front Tyre	225/40R18	PIRELLI	6
R/H Rear Tyre	225/40R18	PIRELLI	6
L/H Rear Tyre	225/40R18	PIRELLI	6

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	10/06/2024	Inspection Date	28/06/2024
Survey held at	PROFI AUTOMOTIVE BLK 10 KAKI BUKIT ROAD 2 #01-05 FIRST EAST CENTRE SINGAPORE 417868		

5a.	Remarks
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.	
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.	

5b.	Estimate Days of Repair
ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days	