

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of First Submission	22/11/2024 16:16 (SGT)
Reported by	Actual Driver
Date of Accident	22/11/2024 10:45 (SGT)
Exact Location of Accident	Bishan Rd, Singapore
Additional Location Information	TOWARDS BRADDELL
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA7804B
-----------------------------------	----------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Company Reg No	199303821R
Email Address	fleetsafety@cdgtaxi.com.sg
Mobile Phone No	(Phone) +65-98426613
Alternative Phone No	(Office) +65-65508768

VEHICLE PARTICULARS

Manufacturer	Hyundai
Model	Ae ioniq
Variant	HEV FL 1.6 DCT
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Reporting only
Vehicle Category	Taxi
Transmission	Auto
CC	1580
Vehicle Fuel	Petrol-Electric
First Registration Date	-
Chassis no	KMHC851CVLU190920
Effective Date/Time of Ownership	-

INSURANCE COMPANY

Name of Insurance Company	MS First Capital Insurance Ltd
Policy Number / Cover Note Number	D-24101861MFCT

DRIVER

Name of Driver	YEO CHEOW HWA
NRIC No	S1160937F
Date Of Birth	29/02/1956
Occupation	Outdoor
Driving Pass Date	13/04/1977
Driving License Pass Class	3
Driving License Validity	Valid
Driving experience	47 YEARS AND 7 MONTHS
Gender	Male
Mobile Number	(Phone) +65-98426613
Alt. Phone Number	-
Email Address	fleetsafety@cdgtaxi.com.sg
Address	BLK 436 JURONG WEST AVE 1 #05-460
Address complement	-
Postcode	640436
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Change/cross lane
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

ON 22.11.2024 AT ABOUT 1045HRS VEHICLE A SHA7804B WAS ALONG BISHAN ROAD IN THE DIRECTION TOWARDS BRADDELL. VEHICLE A SIGNAL LEFT AND FILTERED IN WHEN VEHICLE B GBL510H FROM BEHIND LEFT SPEED UP. VEHICLE B RIGHT FRONT SIDE SWIPE VEHICLE A LEFT CENTRE. NO ONE IS INJURED. SCENE PHOTOS TAKEN. NO PARTICULARS EXCHANGED.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	FILE IS NOT SUITABLE

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBL510H
Vehicle Manufacturer	Toyota
Vehicle Model	HIACE DX 2.8 AUTO
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	RIGHT FRONT
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	2


Describe Circumstances of the Accident

ON 22.11.2024 AT ABOUT 1045HRS VEHICLE A SHA7804B WAS ALONG BISHAN ROAD IN THE DIRECTION TOWARDS BRADDELL. VEHICLE A SIGNAL LEFT AND FILTERED IN WHEN VEHICLE B GBL510H FROM BEHIND LEFT SPEED UP. VEHICLE B RIGHT FRONT SIDE SWIPE VEHICLE A LEFT CENTRE. NO ONE IS INJURED. SCENE PHOTOS TAKEN. NO PARTICULARS EXCHANGED.


Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date &
Time



Driver's Signature (If driver is not the policyholder) / Date
& Time 22.11.2024. 1230 HRS



Witnessed by Reporting Centre
Personnel









