

(08/11/13) Wef

ASS. REC. BY:

REF: C0/11124060295/Rua3

C
6980

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBH 55246

at Workshop m/s CYLUG & CARRIAGE

of

209, PANDAN GARDEN

Insured:

111

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

GIA / PR Seen:

Est. Repairs:

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

GBH 55246

Yr Regn: 2018 / July

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

PICK-UP

Make: MITUBAISHI L200 D-C 2.4 AT cc 2442

Colour: WHITE

AC: Insured / Std / NI / NA

Sp. Reading: 094211

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MMZJ4KL10HH024999

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: MIP / S/Rim / STD A/Rim or

Tyre Size:

F:

245/70R16

R:

22

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

FIRENZA

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

28/05/24

D.O.I.

10/07/24

Survey held at

PG

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

REAR N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIM 5-63K

Date/Time, File Pass to?



Prel. Report



Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

S + RS \$

Photos

Others

Report Format :

Lump Sum / I.B.I. (\$

TOTAL



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 64739722



ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Altus Facilities Engineering Pte Ltd 9 Dairy Farm Heights #06-22 The Sky Woods Singapore 677670 Billing Address : 124 Pioneer Ro Contact No Mobile: 96670956	Cust No/Name	/Altus Facilities Engineering Pt
	Reg No/Reg Date	GBH5524G / 09/07/2018
	Date In/Mileage	/ 0
	Chassis No	MMCJYKL10HH024999
	Engine No	4N15UCA0948
	Make/Model	MITCV/17MY L200 D/CAB 2.4 AT (T95)
	Colour/Trim	W03 POLAR WHITE SOL/ BK/ BLACK/GREY

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00147	Cash	10/07/2024/ 16:10	TLL	1210/ Lim Teng Keat	50700			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
Z TEXT								
TP CLAIM III								
DOA 25/05/2024								
SUR								
OO REPAIR DAYS								
E PNT88000								2860 6400.00
TO REPLACE CARGO DOOR, REAR BUMPER, REAR REINFORCEMENT,								
REAR LHS FENDER, REAR END PANEL								
TO REPAIR ACCIDENT AFFECTED AREA								
E PNT98000								1650 2200.00
PAINT WORK ON CARGO DOOR, REAR LHS FENDER, REAR END PANEL								
M SUNDRY								? 180.00
TO REPLACE REAR PARKING SENSOR								
E PNT88000								120 180.00
TO R&R REAR CAMERA								
M SUNDRY								85.00
TO SUPPLY REAR NUMBER PLATE WITH CASING								
M SUNDRY								50.00
C&C EMBLEM								
M SUNDRY								20 50.00
SUNDRIES								
M	FACE,RR BUMPER				1.00	1074.00	00.00	1074.00
M	COVER,RR BUMPER				1.00	45.00	00.00	45.00
M	COVER,RR BUMPER,LH				1.00	35.00	00.00	35.00
M	COVER,RR BUMPER,RH				1.00	35.00	00.00	35.00
M	REINFORCEMENT,RR BUMPER				1.00	703.00	00.00	703.00
M	GATE,RR BODY,RR				1.00	1301.00	00.00	1301.00
M	MARK,THREE-DIA				1.00	74.00	00.00	74.00
M	MARK,DIESEL				1.00	31.00	00.00	31.00
M	DECAL,COMMON RAIL				1.00	4.00	00.00	4.00
M	MARK,L200				1.00	31.00	00.00	31.00
M	MARK,MITSUBISHI				1.00	66.00	00.00	66.00
M	SILL,RR BODY FLOOR RR END				1.00	439.00	00.00	439.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 64739722



Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
Altus Facilities Engineering Pte Ltd 9 Dairy Farm Heights #06-22 The Sky Woods Singapore 677670 Billing Address : 124 Pioneer Rd Contact No Mobile: 96670956	<table> <tr> <td>Cust No/Name</td><td>/Altus Facilities Engineering Pt</td></tr> <tr> <td>Reg No/Reg Date</td><td>GBH5524G / 09/07/2018</td></tr> <tr> <td>Date In/Mileage</td><td>/ 0</td></tr> <tr> <td>Chassis No</td><td>MMCJYKL10HH024999</td></tr> <tr> <td>Engine No</td><td>4N15UCA0948</td></tr> <tr> <td>Make/Model</td><td>MITCV/17MY L200 D/CAB 2.4 AT (T95)</td></tr> <tr> <td>Colour/Trim</td><td>W03 POLAR WHITE SOL/ BK/ BLACK/GREY</td></tr> </table>	Cust No/Name	/Altus Facilities Engineering Pt	Reg No/Reg Date	GBH5524G / 09/07/2018	Date In/Mileage	/ 0	Chassis No	MMCJYKL10HH024999	Engine No	4N15UCA0948	Make/Model	MITCV/17MY L200 D/CAB 2.4 AT (T95)	Colour/Trim	W03 POLAR WHITE SOL/ BK/ BLACK/GREY
Cust No/Name	/Altus Facilities Engineering Pt														
Reg No/Reg Date	GBH5524G / 09/07/2018														
Date In/Mileage	/ 0														
Chassis No	MMCJYKL10HH024999														
Engine No	4N15UCA0948														
Make/Model	MITCV/17MY L200 D/CAB 2.4 AT (T95)														
Colour/Trim	W03 POLAR WHITE SOL/ BK/ BLACK/GREY														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00147	Cash	10/07/2024/ 16:10	TLL	1210/ Lim Teng Keat	50700
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M SILL,RR BODY FRAME ?		1.00	350.00	00.00	350.00
M GATE,RR BODY SIDE,LH <i>bur</i>		1.00	1182.00	00.00	1182.00
M PNL,R/BODY SIDE SKRT,RR LH ?		1.00	128.00	00.00	128.00
M LAMP ASSY,COMB,RR LH <i>ca</i>		1.00	488.00	00.00	488.00
M LAMP ASSY,COMB,RR RH <i>X</i>		1.00	488.00	00.00	488.00
M LAMP ASSY,LICENSE PLATE ?		1.00	32.00	00.00	32.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SURVEYOR NAME: *Farah - Hp 90010068*SURVEYOR SIGNATURE: *Farah*DATE: *10/07/24*REMARKS: *6 days**Reg by part*

Confirm & accepted by

	Nett	15,651.00
9% GST on	15651.00	1408.59

Total Payable	17,059.59
---------------	-----------

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	698D
Vehicle Details	
Vehicle No.:	GBH5524G
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Jul 2024
Vehicle Make:	MITSUBISHI
Vehicle Model:	L200 DOUBLE CAB 2.4 AT
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	4N15UCA0948
Chassis No.:	MMCJYKL10HH024999
Maximum Power Output:	-
Open Market Value:	\$25,461.00
Original Registration Date:	09 Jul 2018
First Registration Date:	09 Jul 2018
Transfer Count:	1
Actual ARF Paid:	\$27,646.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	08 Jul 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$34,001.00
COE Rebate Amount:	\$13,569.00
Total Rebate Amount:	\$13,569.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 11 Jul 2024

OK



Mitsubishi Triton L200 Double-Cab 2.4A

\$81,800 Instalment \$1,742/mth

PREMIUM AD

♡ Shortlist

📅 Loan Calculator

Overview Financial Photo Research

Depreciation	ⓘ \$19,690 / year
Reg. Date	05-Sep-2018 (4yrs 1mth 24days COE left)
Lifespan	ⓘ 04-Sep-2038
Manufactured	ⓘ 2018
Mileage	<u>86,446 km</u> (14.8k / year)
Transmission	Auto
Engine Cap	2,442 cc
Curb Weight	ⓘ <u>1,800 kg</u>
Fuel Type	Diesel
COE	ⓘ \$26,120
OMV	ⓘ \$25,629
ARF	ⓘ \$27,881
Dereg Value	ⓘ \$10,849 as of today
No. of Owners	ⓘ 2