

Vehicle ident no.
SNK6418R

Repair order no.
R016716

Technician
MIRAI AUTO

Date
21.11.24

License plate no.

First reg. date

Model

Odometer reading: km/miles

Toyota : Altis : with 215/45R17 Tire : Indonesia and
Malaysia : 2016-

1

Complaints or reason for alignment check

			Before	Target Data	Actual
Rear axle	Camber	left		-1°29' +/-0°30'	-1°22'
		right			-1°15'
		cross		0°00' +/-0°30'	-0°07'
	Toe	left		0°07' +/-0°06'	-0°02'
		right			-0°03'
		total		0°15' +/-0°12'	-0°05'
	Geometrical driving axis			0°00'	0°00'
Front axle	Camber	left		-0°35' +/-0°45'	-0°17'
		right			-2°37'
		cross		0°00' +/-0°30'	2°19'
	Caster	left		2°58' +/-0°45'	
		right			
		cross		0°00' +/-0°30'	
	SAI	left		12°34'	
		right			
		cross		0°00'	
	Track differential angle	left			
		right			
	Toe	left		0°00' +/-0°05'	0°04'
		right			-1°21'
		total		0°00' +/-0°09'	-1°17'
	Setback			0°00'	
	Max steering lock	left steer	left	-38°11' +/-2°00'	
			right	32°49' +/-2°00'	
			left	32°49' +/-2°00'	
		right steer	right	-38°11' +/-2°00'	