



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD  
INCOME CENTRESINGAPORE 189557

ATTN: CHARLOTTE CHEW

Ref: CS/INC24110526/Aqh3e2(N)

Date: 27/02/2025

Code: INC

#### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SGQ 2353X	<b>Veh. Inspected</b>	SLR 505Z
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	MT/1305675-002	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	CHARLOTTE CHEW	<b>Assign Date</b>	25/11/2024

#### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	B.M.W. 420I GRAN COUPE	<b>c.c</b>	1998
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2017
<b>Chassis No.</b>	WBA4H32040BH11116	<b>Colour</b>	WHITE
<b>Odometer</b>	87784 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		

#### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	265/30 R19	MICHELIN	6 mm
<b>L/H Front Tyre</b>	265/30 R19	MICHELIN	6 mm
<b>R/H Rear Tyre</b>	265/30 R19	MICHELIN	6 mm
<b>L/H Rear Tyre</b>	265/30 R19	MICHELIN	6 mm

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  
DAMAGES SEE DETAILS.

#### 5. General Information

<b>Accident Date</b>	24/11/2024	<b>Inspect Date / Time</b>	26/11/2024 ( 05:59 PM )
<b>Survey held at</b>	JL PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875		

#### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

#### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **9 Working Days**