

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile  |   |  |                 |                       |  |
|--|---|--|-----------------|-----------------------|--|
| MS   | INCOME INSURAN                          | CE LTD   | Ref:            | CS/INC24110527/Uvh3e2 |  |
|  | 75 BRAS BASAH R                         |  | Date:           | 05/12/2024            |  |
|  | INCOME CENTRES                          | SINGAPORE 189557   | Code:           | INC                   |  |
| 1.   | Policy Particulars :- THIRD PARTY CLAIM |  |                 |                       |  |
|  | Insured Veh.                            | YQ 3040D   | Veh. Inspected  | SLF 9739U             |  |
|  | Policy No.                              | -  | Coverage        | 0                     |  |
|  | Claim No.                               | MT/1305816-001   | Excess          | \$0.00                |  |
|  | Assign From                             | ENG HUEY HUE   | Assign Date     | 25/11/2024            |  |
| 2.   | . Vehicle Details                       |  |                 |                       |  |
|  | Make & Model                            | HONDA VEZEL (A)  | C.C             | 1496                  |  |
|  | Engine No.                              | L15B4404710  | Year of Reg.    | 16/09/2016            |  |
|  | Chassis No.                             | RU11204710   | Colour          | BLUE                  |  |
|  | Odometer                                | 287529 KM  | Steering        | IN ORDER              |  |
|  | Brakes                                  | IN ORDER   | General         | GOOD                  |  |
|  | Modification(s)                         | RIMS: SPORTS RIM   |                 |                       |  |
| 3. Conditions of Tyres   |   |  |                 |                       |  |
|  |   | Size   | Make            | Balance (mm)          |  |
|  | R/H Front Tyre                          | 215/60R16  | FALKEN          | 6                     |  |
|  | L/H Front Tyre                          | 215/60R16  | FALKEN          | 6                     |  |
|  | R/H Rear Tyre                           | 215/60R16  | FALKEN          | 6                     |  |
|  | L/H Rear Tyre                           | 215/60R16  | FALKEN          | 6                     |  |
| 4.   | Description of Damages                  |  |                 |                       |  |
| THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.  |   |  |                 |                       |  |
| DAMAGES SEE DETAILS.   |   |  |                 |                       |  |
| 5.   |   | General Information  |                 |                       |  |
|  | Accident Date                           | 21/11/2024   | Inspection Date | 26/11/2024 (14:36)    |  |
|  | Survey held at                          | y held at JSSM AUTOSOLUTIONS PTE LTD<br>8 KAKI BUKIT AVENUE 4, #02-13, PREMIER @ KAKI BUKIT SINGAPORE 415875 |                 |                       |  |
| 5a. Remarks  |   |  |                 |                       |  |
| A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |   |  |                 |                       |  |
| 5b. Estimate Days of Repair  |   |  |                 |                       |  |
| FORTIMATED MODIMAL DEDIOD FOR DEDAID: 2 Working Days   |   |  |                 |                       |  |

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days