Asst. Sign: REF:

ASSIGNMENT

From: Date:

Estim Cost:

OD / TPFT / TP RES / CD RES / EVA / INV / MV

To Insp Vehicle No:

at Workshop/s

at

Insured:

Policy No.

Claim's No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Vals: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SNQ5250G Yr Regn: 2024 April

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Toyota Sienta Hybrid C.C. 1490

Colour White A/C: Insured / Std / NI / NA

Sp.Reading 57855. T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JTDBBBA300L001655

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/65R15 Toyo

R: 185/65R15 Toyo

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Triangle

Front		Rear	
R/Bal.	06 mm	R/Bal.	06 mm
L/Bal.	06 mm	L/Bal.	06 mm
D.O.A.		D.O.I.	26/11/24

Survey held at HHHB

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP Lon Pac
	MV : 158K
	PV : 94.1K
	Nett : 63.9K

COE Expiry :

Estimate given during : Yes ( )
1st Survey : No ( )

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐ : Preli. Report

☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Inve ($)

Report Format :

Survey Fee:	
Transportation: $ + R$ $	
Photos	
Others	