

ASSIGNMENT

From: _____ Date: _____
 Est: _____
 OD / TP RES / OD RES / EVA / INV / MV
 To in TP Vehicle No: _____
 at W km/s _____
 of _____
 Insured: _____
 Policy No: _____
 Claim No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Vcl: _____

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Report _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Veh No: GBM3405D Yr Regn: 2023, March.
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Honda N Van CC 658
 Colour: Red A/C: Insured / Std / NI / NA
 Sp. Reading: 49407 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JJ/6004166
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 155R12C
 R: 155R12C

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Hankook
 Front _____ Rear _____
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 26/11/24
 Survey held at Best Solution
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP Budget. Direct.</u>
	<u>COE Expiry</u>
	<u>Estimate given during : Yes (✓)</u>
	<u>1st Survey : No ()</u>
	<u>MV :</u>
	<u>PV :</u>
	<u>Nett :</u>

Date/Time, File Pass to? ☐ : Preli. Report
☐ : Final Report
 1) _____
 Date/Time, File Return to?
 2) _____
 Days Of Repair: _____
 Resurvey No. of Trip: _____
 Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Insp (\$ _____)
 Survey Fee: _____
 Transportation: _____
 Photos _____
 Others _____

BEST Solution Autocare Pte Ltd

53 Ubi Avenue 1, #03-01, Paya Ubi Industrial Park, Singapore 408934

Business Reg. No.: 201626438D

☎ 6744 0777

☎ 6744 2377

Estimate Quotation

Quotation No	Nov 001/2024
Date	26/11/2024
Vehicle No	GBM3405D
Make / Model	Honda Nvan

To: Auto & General Insurance (Singapore) Pte Ltd
Address: 190 Clemenceau Avenue #03-01 Singapore Shopping Centre Singapore 239924

Qty	DESCRIPTION	Amount
	Items	
1 pc	rear end panel top garnish ?	\$ 1,696.00
1 pc	tailgate <i>Detached</i>	\$ 60 80.00
1 pc	tailgate glass sealant <i>new</i>	\$ 95.00
1 set	company sticker / logo <i>new</i>	\$ 95.00
1 pc	website sticker <i>new</i>	\$ 92.00
1 pc	tailgate "NVAN" emblem <i>new</i>	\$ 90.00
1 pc	tailgate "centre" emblem <i>new</i>	\$ 70.00
1 pc	70 km/h sticker <i>new</i>	\$ 70.00
1 pc	5 pax sticker <i>new</i>	\$ 400.00
4 pcs	reverse sensor <i>Detached</i>	\$ 400.00
1 set	reverse camera <i>new</i>	\$ 689.00
1 pc	rear centre bumper <i>Detached</i>	\$ 1,232.00
2 pcs	rear side bumper (corner) RH ?	\$ 476.00
1 pc	o/s tail lamp <i>Cracked</i>	\$ 986.00
1 pc	exhaust silencer	\$ 150.00
2 pcs	rear bumper side retainer <i>new</i>	\$ 30 80.00
1 set	rear bumper clip <i>new</i>	\$ 211.00
1 pc	tailgate w/strip ?	\$ 145.00
1 pc	tailgate inner garnish <i>new</i>	\$ 80.00
1 pc	o/s sliding door rail stopper <i>new</i>	\$ 625.00
1 pc	full wrap graphic <i>new</i>	
	Labour Charge	
1	to dismantle damaged parts, panel beat, repair	\$ 1,500.00
2	to putty and spray painting on affected area	\$ 1,500.00
3	anti rust	\$ 100.00
4	electrical wiring check	\$ 80.00
5	remove & refit reverse camera	\$ 80.00
6	remove & refit reverse sensor	\$ 80.00
7	remove & refit tailgate glass	\$ 80.00
8	remove & refit tailgate mechanism & fitting	\$ 200.00
		\$ 11,382.00

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

BEST SOLUTION AUTOCARE PTE LTD

Authorized Signature

Adm
L/s 26/11/24.
05 Days