



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD

INCOME CENTRESINGAPORE 189557

ATTN: AZHARI

Ref: CS/INC24110534/Anh3e2(N)

Date: 03/01/2025

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMS 4303X	Veh. Inspected	SMV 9242P
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1305306-002	Excess (\$)	0.00
Assign From	AZHARI	Assign Date	25/11/2024

2. Vehicle Particulars & Condition

Make & Model	VOLKSWAGEN PASSAT	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	WVWZZZ3CZKE139596	Colour	BLACK
Odometer	38808 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/40 R18	MICHELIN	6 mm
L/H Front Tyre	245/40 R18	MICHELIN	6 mm
R/H Rear Tyre	245/40 R18	MICHELIN	6 mm
L/H Rear Tyre	245/40 R18	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	21/11/2024	Inspect Date / Time	26/11/2024 (05:34 PM)
Survey held at	TWINCAR AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days