

ASSIGNMENT

Front: _____ Date: _____
 Estm: _____
 OD / TP RES / CD RES / EVA / INV / MV
 To in Vehicle No: _____
 at W/O _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Val: _____
 (Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bel. or Malt Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SmV9242P Yr Regn: 2020, Oct.
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Volkswagen Passat cc 1798
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: 38808 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WVWZZZ3CZKE139596
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 245/40R18
 R: 245/40R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front		Rear	
R/Bal. <u>06</u> mm		R/Bal. <u>06</u> mm	
L/Bal. <u>06</u> mm		L/Bal. <u>06</u> mm	
D.O.A. _____		D.O.I. <u>26/11/24</u>	

Survey held at Twin Car
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP INC</u>
	<u>COE Expiry</u>
	<u>Estimate given during : Yes (✓)</u>
	<u>1st Survey : No ()</u>
	<u>MV :</u>
	<u>PV :</u>
	<u>Nett :</u>
	<u>518Z</u>

Date/Time, File Pass to? ☐ : Prel. Report
☐ : Final Report

Days Of Repair: _____
 Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Inve (\$)

Survey Fee:

Transportation: 3 + R8 \$
 Photos
 Others

Report Format:

Report Form: A.P.P. (C)