



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS AUTO & GENERAL INSURANCE (S) PL	Ref:	CS/AGI24110535/Uqp3m4
(BUDGET DIRECT INSURANCE)	Date:	04/12/2024
190 CLEMENCEAU AVENUE #03-01	Code:	AGI
SINGAPORE SHOPPING CENTRE SINGAPORE 239924		

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMX 4454S	Veh. Inspected	SNK 3696Z
Policy No.	-	Coverage	0
Claim No.	C10033080/CY	Excess	\$0.00
Assign From	CALEEN YIT	Assign Date	26/11/2024

### 2. Vehicle Details

Make & Model	HONDA SHUTTLE 1.5G (A)	C.C	1496
Engine No.	L15B5000728	Year of Reg.	11/01/2017
Chassis No.	GK81100642	Colour	SILVER
Odometer	158044 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195/55R15	GITI	6
L/H Front Tyre	195/55R15	GITI	6
R/H Rear Tyre	195/55R15	GITI	6
L/H Rear Tyre	195/55R15	GITI	6

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	21/11/2024	Inspection Date	27/11/2024
Survey held at	V.Z AUTOMOTIVE PTE LTD - PREMIER @ 8 KAKI BUKIT AVE 4 #04-35 SINGAPORE 415875		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days