



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24110549/Unh3m4
75 BRAS BASAH ROAD	Date:	10/12/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKU 9666D	Veh. Inspected	SKG 1853G
Policy No.	-	Coverage	0
Claim No.	MT/1304055-002	Excess	\$0.00
Assign From	RAJESWARY	Assign Date	25/11/2024

2. Vehicle Details

Make & Model	KIA FORTE K3 1.6A	C.C	1591
Engine No.	G4FGHH692071	Year of Reg.	07/03/2018
Chassis No.	KNAFJ411MJ5761852	Colour	WHITE
Odometer	167506 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	225/45R17	GOODYEAR	6
L/H Front Tyre	225/45R17	GOODYEAR	6
R/H Rear Tyre	225/45R17	MICHELIN	6
L/H Rear Tyre	225/45R17	MICHELIN	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	12/11/2024	Inspection Date	02/12/2024 (09:22)
Survey held at	BLUWEL AUTOMOTIVE SERVICE PL BLK 1 KAKI BUKIT AVE 6 #01-28/53/55/56 (MAIN OFFICE) SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days