

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT					
	INCOME INSURAN	CE LTD	Ref:	CS/INC24110550/Aqh3e2(N)	
	75 BRAS BASAH RINCOME CENTRES	OAD BINGAPORE 189557	Date	: 24/01/2025	
	ATTN: JULIE		Code	e: INC	
1.	. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMU 2921P	Veh. Inspected	SMD 8065K	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	MT/1303705-002	Excess (\$)	0.00	
	Assign From	JULIE	Assign Date	26/11/2024	
2. Vehicle Particulars & Condition					
	Make & Model	HONDA FREED	c.c	1496	
	Engine No.	HIDDEN	Year of Reg.	2018	
	Chassis No.	GB71060150	Colour	WHITE	
	Odometer	80041 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	195/60 R15	DUNLOP	6 mm	
	L/H Front Tyre	195/60 R15	DUNLOP	6 mm	
	R/H Rear Tyre	195/60 R15	DUNLOP	6 mm	
	L/H Rear Tyre	195/60 R15	DUNLOP	6 mm	
4.	. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.				
	DAMAGES SEE DE	ETAILS.		E .	
				1.7	
5.	General Information				
	Accident Date	09/11/2024	Inspect Date / Time	02/12/2024 (01:30 PM)	
	Survey held at	MG SOLUTION PTE LTD			
		23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933			
5a. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days				