

ASS. REG. BY:

Taffin

REF:

CS/CT124110584/TVH3

ASSIGNMENT

From:

Date:

Estimated Cost:

☒ OD ☐ TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

tba

(Client's Record)

Make of Veh:

(Policy Condition)

 Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

\$118K

IDAC Accident Report

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SNJA29C

Yr Regn:

2019, 08

Type: ☒ Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

Mercedes Benz CLA200

c.c 1332

Colour:

White

A/C: Insured / Std / NI / NA

Sp. Reading

85852

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WDD1183872N-018864

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

235 / 35 R19

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

28/11/24

Survey held at

Century Motors

Des. of Damages: Frt / Rear / O/S / N/S / U/G / Rooftop or

Frt, u/c, gearbox

The U/G / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Rep. Format:

Lump Sum / I.B.L. /

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

CENTURY MOTORS PRIVATE LIMITED
INCHCAPE CENTRE
SINGAPORE 128462

Insurer Reference: SNJ929C

Repairer Reference: CM297/SNJ929C

Date calculated: 26/11/2024 5:55 PM

Full Report

Registration: SNJ929C

Printed: 26/11/2024 5:55 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	Income Insurance Limited
Printed by:	Loh Chen Khuan	Currency:	SGD
Claim Reference:	SNJ929C	Date of Incident:	22/11/24
Estimated Repair Time:	14	Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	MERCEDES-BENZ
Model:	CLA (C118)
Sub Model:	CLA 200
Model Sheet Number:	03 L7 44
Registration:	SNJ929C
VIN number:	WDD1183872N018864
Odometer:	

Model Specs

FR PRODUCTION START	DYNAMIC SELECT	ILLUMINAT AMBIENTE	KNEE AIRBAG
INNER HEADLINING	SPORT S-WHEEL LEATH	MODEL 2020	DR MIRROR GPS AERIAL
AIR CON THERMATIC	CRUISE CONTROL	ERM BRAKE ASSIST	TRIM CARBON LOOK
TOUCHPAD	HEADUNIT ASIA	CONNECT 20 MID	DIGITAL INSTRUMENTS
MEDIA DISPLAY	H-LAMP LED HIGH PER	LIGHT-/VIEW PACKAGE	LEATHER PAD ARTICO
FOLDING REAR SEAT	PROGRESSIVE	DOUBLE CUP HOLDER	ELEC FOLD DR MIRRORS
SILL MLDG ILLUMINAT	OUT/IN MIRR AUTO DIM	S/BELT W/WARNING DEV	DRIVER SEAT MEMORY
PASS SEAT MEMORY	LUMBAR SUPPORT	MIRROR PACKAGE	STORAGE BOX
SEAT COMFORT PACKAGE	ADVANTAGE PACKAGE	SUN VISOR SPEC FUNC	REARVIEW CAMERA
ACTIVE CARBON FILTER	KEYLESS GO	LOAD COMPART PACKAGE	TYRE PRESSURE SENSOR
7-SPEED AUTOMATIC	SHIFT PADDLE ON STRG	COMFORT SUSPENSION	TYRES 225/45 R18..W
WHEELS 7.5J X 18 ALU	HANDS-FREE ACCESS	TYRE W/FLAT RUNNING	WIRELESS CHARGER
PEDESTRIAN PROTECT	PARKTRONIC	COMPRESSOR VARIABLE	REAR ARMREST
PARK PACK	SOCKET 12V	CLEAR COAT HARD	BASECOAT CLEAR

Labour

Code	Description	Time Base 10 WU/h		Price = 42.00 SGD/h	
				WU	Price SGD
54-1011 01	SHORT TEST INCLUDES: CONNECT + DISCONNECT STAR DIAGNOSIS, PRINT DATA, DELETE ERROR MEMORY			3.0	12.60
54-7989 01	R + R BATTERY EARTH CABLE (WHEN DISCONNECTING ELECTRIC PLUG AND SOCKET CONNECTIONS)			2.0	8.40
61-1086 01	R + R COMPL LWR ENGINE COMPARTMENT COVER			5.0	21.00
61-1116 01	R + R L/UNDERFLOOR COVER			4.0	16.80

Code	Description	WU	Price SGD
61-1117 01	R + R R/UNDERFLOOR COVER		
61-1127 01	RENEW REAR UNDERBODY COVERING	4.0	16.80
88-1102 01	R + R FRONT BUMPER CPL	4.0	16.80
88-1319 01	ADD FOR R + R FRONT BUMPER (VEHICLE WITH PARKTRONIC)	9.0	37.80
88-1935 01	ADDITION TO R + R FRONT BUMPER (VEHICLE WITH PEDESTRIAN PROTECT)	1.0	4.20
88-1105 01	DIS + ASS FRONT BUMPER (BUMPER REMOVED)	11.0	46.20
88-1364 01	AFTER CHECK: RENEW PARTS IF NECESSARY ADDITION TO FRONT BUMPER DIS + ASS (VEHICLE WITH PEDESTRIAN PROTECT)	1.0	4.20
88-1360 01	ADDITION TO DIS + ASS FRONT BUMPER (VEHICLE WITH PARK ASSISTANT)	3.0	12.60
88-1933 01	ADDITION TO R + R FRONT BUMPER (VEHICLE WITH COLLISION WARN SYS)	1.0	4.20
88-1162 01	ADDITION TO DIS + ASS FRONT BUMPER (VEHICLE WITH ACTIVE BRAKE ASSIST)	1.0	4.20
82-4730 01)	R + R BOTH HEADLAMPS	3.0	12.60
01-2800 04)	R + R ENGINE WITH GEARBOX (FRONT MODULE AND AXLE SHAFTS REMOVED)	26.0	109.20
	INCLUDES: RADIATOR, INTERCOOLER, ENGINE AIR DUCT, ENGINE COVER AND R + R AIR FILTER CPL		
27-2112 01	DETACH + REFIT GEARBOX (ENGINE AND GEARBOX REMOVED)	8.0	33.60
27-2152 ZAX	RENEW AUTOMATIC GEARBOX (REMOVED)	4.0	16.80
NO NUMBER	R + R FRONT AXLE CARRIER	18.0	75.60
33-1860 01	RENEW FRONT AXLE SUPPORT (REMOVED)	12.0	50.40
83-1762 01	AIR-CONDITIONING SYSTEM DRAIN FLUID, EXHAUST, REFILL, PRESSURE TEST (FOR ALL WORK ON THE SYSTEM)	6.0	25.20
54-2290 ZAX	CALIBRATE FRONT RADAR	2.0	8.40
82-1120 01	ADJUST LED HEADLAMP	7.0	29.40
40-6500 01	ALIGN VEHICLE	8.0	33.60
	INCLUDES: ALIGN FRONT AND REAR TOE AND CAMBER, CHECK FRONT AND REAR VEHICLE LEVEL		

Labour Cost

Panel / Mechanical Labour

Hrs WU
14.40 144.0

604.80

Total of Labour

604.80

Paint

Paint Work

SYSTEM AZT

Time Basis 10 WU/h

Code	Description - BASECOAT CLEAR	WU	Price SGD
	FRONT BUMPER TRIM NEW PART PAINT K1R	13.0	

Paint Material Per Part

Code	Description	Price SGD
0283	FRONT BUMPER TRIM NEW PART PAINT K1R	67.40

Paint Material Per Part

Code	Description	Price SGD
------	-------------	-----------

Labour Cost - Paint

Factor	Hrs	WU	Price SGD
Time Paint		13.0	
Preparation Comp. Work Plastic	0.90	9.0	37.80
Total	10 WU/h	22.0	92.40

Material Cost - Paint

Description	Price SGD
New Part Painting - Plastic K1R	67.40
Material-constant Plastic	16.20
Total	83.60

Spare Parts

Code	Description	Part Number	Part Source	prices as at 2015-06-01	Price SGD
0283	FRONT BUMPER TRIM	118 885 0303 9999	Original	Rx	1,500.00
3941	FR/RR UNDERBODY PROT	NO NUMBER	Original	?	0.00
3945	R/R UNDERBODY PROT	118 684 0000	Original	?	0.00
4283	L/F LWR FLOOR COVER	177 680 8403	Original	?	250.00
4284	R/F LWR FLOOR COVER	177 680 8603	Original	?	250.00
7011	FRONT AXLE SUPPORT	177 620 7101	Original	?	2,800.00
8779	FRONT GRILLE PANEL	118 885 4600	Original	?	350.00
8780	FRONT CENTRE TRIM	247 520 2600	Original	eng	350.00
8852	GEARBOX EXCH	700 370 3500 80	Original	eng	12,000.00
f: OEM Parts	Savings				0.00
n: Non-OEM Parts	Subtotal				17,500.00
u: Used parts	Total				17,500.00

Extras

Code	Description	Price SGD
1000	FRT BUMPER CLIPS	?
1001	AUTO FLUID	rec 350.00*
	Total Extras	380.00

Final Calculation

	SGD	SGD
Parts		
Total Parts	17,500.00	17,500.00
Labour Time Base 10 WU/h		
Total 144.0 WU X 42.00 SGD/h	604.80	
Total of Labour		604.80
Total Of Extras		380.00
Paint Work Time Base 10 WU/h		
Labour Cost 22.0 WU X 42.00 SGD/h	92.40	
Material Cost	83.60	
Total Paint Including Material		176.00
Repair Cost Excludes GST		18,660.80
GST (+9.00%)		1,679.47
Repair Cost Included GST		20,340.27

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

At the time of repair, the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin 97495749

Not Authorise

28/11/24 3pm

Ex: to be advise

Tanpin c/khauto.com

Resurvey new / old parts together.
 8-10 days



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of First Submission	25/11/2024 17:13 (SGT)
Reported by	Both Policyholder and Actual Driver
Date of Accident	22/11/2024 15:00 (SGT)
Exact Location of Accident	KJE, Singapore
Additional Location Information	TOWARDS TUAS, JOHOR
Country/State of Loss	Malaysia

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SNJ929C
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	HO JOON KEONG (HE JUNQIANG)
NRIC No	SXXXX505F
Email Address	CALVIN7381@HOTMAIL.COM
Mobile Phone No	(Phone) +65-96686846
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Mercedes
Model	Cla200
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	1332
Vehicle Fuel	-
First Registration Date	-
Chassis no	WDD1183872N018864
Effective Date/Time of Ownership	-

INSURANCE COMPANY

Name of Insurance Company	China Taiping Insurance (Singapore) Pte. Ltd.
Policy Number / Cover Note Number	DMPCSNA00014732401

DRIVER

Name of Driver	HO JOON KEONG (HE JUNQIANG)
NRIC No	SXXXX505F
Date Of Birth	03/07/1981
Occupation	Indoor
Driving Pass Date	27/02/2006
Driving License Pass Class	3
Driving License Validity	Valid
Driving experience	18 YEARS AND 9 MONTHS
Gender	Male
Mobile Number	(Phone) +65-96686846
Alt. Phone Number	-
Email Address	CALVIN7381@HOTMAIL.COM
Address	68 CHOA CHU KANG AVE 5 #13-14
Address complement	-
Postcode	688195
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Hit by fallen tree / Other objects
Weather Conditions	Raining
Road Surface	Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	1
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	No
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO THE ATTACHMENT

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/are be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Actual Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

Sketch Plan

Unable to provide sketch



vJun2022

1

Describe Circumstance of the Accident

Refer to the attachment.

Declaration
I/We declare the foregoing particulars are true in every respect.

	
Policyholder's Signature / Date & Time	Actual Driver's Signature (if driver is not the policyholder) / Date & Time
	Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)

On 22 Nov 2024, at about 1500hrs, when I was driving along KJE towards Tuas, suddenly I heard a sound. Due to the heavy rain I could not stop at the road shoulder to do a check and continued my trip to Johor Bahru. After that my car was parked at the car park of Geobay Hotel.

On 23 Nov 2024 at about 0730, when I returned to my car, I could start my car but when the gear is engaged the car is not moving so I arranged tow truck to tow to Singapore on 24 Nov 2024 as the only date available.

