



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24110604/Uqp3e2
16 RAFFLES QUAY	Date:	27/12/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 4755M	Veh. Inspected	SJV 8095P
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24010337MFCT	Excess	\$0.00
Assign From	CAROLINE	Assign Date	28/11/2024

2. Vehicle Details

Make & Model	NISSAN SYLPHY 1.5 (A)	C.C	1498
Engine No.	HR15294026B	Year of Reg.	09/02/2010
Chassis No.	JN1BAAG11Z0110704	Colour	BLACK
Odometer	215920 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195/65R15	YOKOHAMA	6
L/H Front Tyre	195/65R15	YOKOHAMA	6
R/H Rear Tyre	195/65R15	YOKOHAMA	6
L/H Rear Tyre	195/65R15	YOKOHAMA	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	22/11/2024	Inspection Date	28/11/2024
Survey held at	AUTOLUTION INDUSTRIAL PTE LTD 19 UBI ROAD 4 SINGAPORE 408623		

5a. Remarks
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair
ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days