

PLEASE ARRANGE TO SURVEY
VEHICLE AT PANDAN ROAD

Selamatshahh
CLAIM DEPARTMENT
DID : 66547727
FAX :

Date : 28/11/2024
To : ECICS LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd
: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : 1 Accident Date : 19/11/2024

Vehicle No : GBJ-7242-X Make & Model : NISSAN NV350 PANEL VAN 2.5 DIESEL G (A) F

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
Nett Item			
1	FRONT BUMPER	RESTORE	
1	B PILLAR LH	RESTORE	
1	SLIDING DOOR LH	RESTORE	
1	ROCKER PANEL LH	RESTORE	
	Sub Total	0.00	
	Discount 10% On Parts	(0.00)	
Special Nett Item:			
1	ADVERTISEMENT STICKER	400.00	300

Date : 28/11/2024
To : ECICS LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd
: SOMPO INSURANCE SINGAPORE PTE. LTD.
Certificate No : 1 Accident Date : 19/11/2024
Vehicle No : GBJ-7242-X Make & Model : NISSAN NV350 PANEL VAN 2.5 DIESEL G (A) I

ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	400.00	
	Labour & Misc		
	LABOUR TO FACILITATE REPAIR		
	TO RESPRAY AFFECTED AREAS		
	RUST PROOFING		
	Sub Total	1350.00	
		1,750.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Remarks:

3 days - P/P

SUB TOTAL
GST 9.0 % 157.50
TOTAL 1,907.50

Surveyor's name: Rasm - Hp 92000008

Principal's name: ETHOZ Group Ltd

Survey Date & Time: 29/11/24