

08/11/13) We
ASS. REC. BY:

REF:

CS/ICS 24110607/Rnp3

9439

ASSIGNMENT

From:

Date:

Estimated Cost:

OD (TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBJ 7242X

at Workshop m/s ET Hu2

of PANAM R7

Insured: ICS

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: 54K

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

GBJ 7242X

Yr Regn: 2019 July

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

NISSAN NV350 P.V

c.c. 2488

Colour

BLACK

AC: Insured / Std / Nil / NA

Sp. Reading

16070

T/Radio: Insured / Std / Nil / NA

Eng/No:

C/No:

JN/MC2E2620031486

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 195R15

R:

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSN / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6 mm

R/Bal.

6 mm

L/Bal.

6 mm

L/Bal.

6 mm

D.O.A

19/11/24

D.O.I

29/11/24

Survey held at

PANAM LUL

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REDGIRL LING - 42K

We will be advising our principal a cost of repair P/P \$1,430.00 /- with 03 days of repair
(red, \$32018%)

Date/Time, File Pass to?

☐

: Prel. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair: 3

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

): \$ + RE \$

☐

: Interview (\$

): Photos

☐

: Tech. Invs (\$

): Others

☐

: Weekend (\$

):

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

PLEASE ARRANGE TO SURVEY
VEHICLE AT PANDAN ROAD

Selamatshahh
CLAIM DEPARTMENT
DID : 66547727
FAX :

Date : 28/11/2024
To : ECICS LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd
: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : 1 Accident Date : 19/11/2024

Vehicle No : GBJ-7242-X Make & Model : NISSAN NV350 PANEL VAN 2.5 DIESEL G (A) F

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
-----	-------------	-------------------	---------------

Nett Item

1	FRONT BUMPER	RESTORE
1	B PILLAR LH	RESTORE
1	SLIDING DOOR LH	RESTORE
1	ROCKER PANEL LH	RESTORE

Sub Total

0.00

Discount 10% On Parts

(0.00)

Special Nett Item

1 ADVERTISEMENT STICKER

~~400.00~~

300

Date : 28/11/2024
To : ECICS LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd
: SOMPO INSURANCE SINGAPORE PTE. LTD.
Certificate No : 1 Accident Date : 19/11/2024
Vehicle No : GBJ-7242-X Make & Model : NISSAN NV350 PANEL VAN 2.5 DIESEL G (A) I

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	400.00	
	<u>Labour & Misc</u>		
	LABOUR TO FACILITATE REPAIR		
	TO RESPRAY AFFECTED AREAS		
	RUST PROOFING		
	Sub Total	1350.00	
		1,750.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

~~600.00~~ 500
~~700.00~~ 600
~~50.00~~ 30

Remarks:

3 days - P/P

SUB TOTAL
GST 9.0 % 157.50
TOTAL 1,907.50

Surveyor's name: Rame - Hp 9266688

Principal's name: ETHOZ Group Ltd

Survey Date & Time: 29/11/24

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	943G
Vehicle Details	
Vehicle No.:	GBJ7242X
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Dec 2024
Vehicle Make:	NISSAN
Vehicle Model:	NV350 PANEL VAN 5DR 2.5 5AT
Primary Colour:	Black
Manufacturing Year:	2019
Engine No.:	YD25055309B
Chassis No.:	JN1MC2E26Z0031486
Maximum Power Output:	-
Open Market Value:	\$26,544.00
Original Registration Date:	29 Jul 2019
First Registration Date:	29 Jul 2019
Transfer Count:	1
Actual ARF Paid:	\$1,328.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	28 Jul 2029
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$25,502.00
COE Rebate Amount:	\$11,873.00
Total Rebate Amount:	\$11,873.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 01 Dec 2024

OK



Nissan NV350 2.5M

\$54,988 Instalment \$1,052/mth

Shortlist

Loan Calculator

- Overview
- Financial
- Photo
- Research

Depreciation	\$11,850 / year
Reg. Date	23-Jul-2019 (4yrs 7mths 21days COE left)
Lifespan	22-Jul-2039
Manufactured	2019
Mileage	-
Transmission	Manual
Engine Cap	2,488 cc
Curb Weight	1,800 kg
Fuel Type	Diesel
COE	\$23,369
OMV	\$25,655
ARF	\$1,283
Dereg Value	\$10,846 as of today
No. of Owners	1
Type of Veh	Van