

ASS. REC. BY:

REF:

AG2/

CS/AGI 24110612/Knp3

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 833k

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SGV 502U Yr Regn: 11.18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Bmw 216d C.C. 1496Colour: White A/C: Insured / Std / NI / NASp. Reading: 258233 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBA 2E320205B45441Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size: F: 215/558R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Fairroad

Front: _____ Rear: _____

R/Bal. 8 mm R/Bal. 8 mmL/Bal. 8 mm L/Bal. 8 mmD.O.A. 16/11/24 D.O.I. 17/2/2025

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

14/2 11:00 AM @ 600/1 Cebu (Red. \$4954.85, 891)

Date/Time, File Pass to?

☐ : Prell. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 2

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S - RS. SI

Fees

Others

TOTAL

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

辉 陽 汽 車 有 限 公 司
HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
GST Reg No. 201629438M

Auto & General
LKK
17/02/25
Monday

16/11/2024

Owner: HYMS CAR LEASING PTE LTD

Not Notwork
11/12/2024 @ 600h
Rehny After Rain
2 days

ESTIMATE TO REPAIR BMW 216 - SGV502U

1pc	rear bumper
1pc	rear bumper chrome
1pc	rear bumper diffuser
2pcs	rear bumper side retainer @ \$85.00
1pc	rear bumper centre bracket
1pc	rear bumper reinforcement

R	\$	1,850.00	R
nd	\$	258.00	✓
in	\$	850.00	X
in	\$	170.00	X
in	\$	185.00	X
R	\$	850.00	X

\$ 4,163.00

\$ 208.15

\$ 3,954.85

less 5%

spray painting
labour charges
Total

\$	800.00	2501
\$	800.00	2201
\$	5,554.85	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

