

MOTOR SURVEY ASSIGNMENT

Date	28/11/2024	Our Ref No.	D24010413MFCT
Accident Date	26-11-2024	Claim Type	Third Party
Insured Vehicle	SHC1299M	Third Party Vehicle	FBM3943S
Survey Location	BAN HOCK HIN CO PTE LTD BLK 8 DEFU SOUTH STREET 1, #04-28 JTC DEFU INDUSTRIAL CITY, S'PORE 533758	Contact Person	Stephanie Gan
Contact No.	62816520	Fax No.	62812830

Survey Type Without Prejudice - liability clear

Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD
Contact Person	Fax No. 68416315
Contact Number	62563561

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

Encl. Estimate & TP GIA Report

Cc : Workshop	BAN HOCK HIN CO PTE LTD	Attention	Stephanie Gan
Officer Incharge	SERENE		

IMPORTANT NOTE

Kindly submit the survey report by **email only** to surveyor@msfirstcapital.com.sg within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.