## **SINGAPORE ACCIDENT STATEMENT**

#### **IMPORTANT NOTICE**

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

  4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 4. The issue and acceptance of this is form by instrained companies.
   5. Any false reporting may be referred to the Police for investigation.
   6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### **ACCIDENT STATEMENT**

Date of First Submission 26/11/2024 18:36 (SGT) Reported by **Actual Driver** Date of Accident 25/11/2024 09:00 (SGT) Exact Location of Accident Singapore Additional Location Information TANGLIN MALL CARPARK Country/State of Loss Singapore

### **DETAILS OF OWN VEHICLE**

Audi

Vehicle Registration Number **SLK8407H** 

INSURED/POLICYHOLDER

Is company? Yes Name Of Registered Owner KSB SINGAPORE (ASIA PACIFIC) PTE LTD Company Reg No 1XXXXX408C Email Address ANDRE.RICHTER@KSB.COM Mobile Phone No (Phone) +65-97542581 Alternative Phone No

### VEHICLE PARTICULARS

Manufacturer

Model

A6 Variant Exact purpose for which vehicle was being used at time of accident Private use Are you claiming under your own insurance policy for repair to Yes your vehicle? Vehicle Category Private car Transmission Auto CC 2000 Vehicle Fuel Petrol First Regisration Date 14/12/2020

Chassis no WAUZZZF27MN012680

Effective Date/Time of Ownership

INSURANCE COMPANY

Name of Insurance Company AIG Asia Pacific Insurance Pte. Ltd. Policy Number / Cover Note Number

DRIVER

Name of Driver	RICHTER ANDRE
Passport No/FIN	GXXXX237K
Date Of Birth	22/09/1973
Occupation	Indoor
Driving Pass Date	04/02/2016
Driving License Pass Class	3
Driving License Validity	Valid
Driving experience	8 YEARS AND 9 MONTHS
Gender	Male
Mobile Number	(Phone) +65-97542581
Alt. Phone Number	(1 Holic) 100-07042001
Email Address	- ANDRE.RICHTER@KSB.COM
Address	46 FABER AVE
Address complement	401 ADEN AVE
Postcode	129550
Is the driver the policyholder?	
	No Franksis
If No, Relationship of the Driver with the Insured  Does Driver Own Other Vehicles?	Employee
	No
Vehicle Registration Number of Other Vehicle Owned by Driver	
Insurance Company of Other Vehicle Owned by Driver	-
insurance Company of Other Vehicle Owned by Driver	-
OFNEDAL INFORMATION OF THE ACCIDENT	
GENERAL INFORMATION OF THE ACCIDENT	
T (A : 1 ·	
Type of Accident	Collided into Property
Weather Conditions	Clear
Road Surface	Dry
OTHER INFORMATION	
OTHER IN ORIGINATION	
Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	1
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	NO
Was any other vehicle or property damaged?	- No
Number of Passengers (Including Driver)	No 1
Has the driver been approached by unknown person(s)	I
	No
soliciting/offering accident claims assistance? Translator's name	NO
Translator's ID	-
Translator's phone number	
Translator's email	
Original language used in the statement	
Original language used in the statement	-
DETAILS OF POLICE ACTION	
Was the accident reported to the police?	No
Was notice of intended Prosecution given?	
If yes, against whom?	
n yoo, agamat whom:	-
CIRCUMSTANCES OF ACCIDENT	
CINCUMOTANCES OF ACCIDENT	
CADDADK ACCIDENT WITH CONCRETE DILLAR TOOK THE	ODNED TO EADLY AND STEEDED LEFT REFORE THE CARLANA
	ORNER TO EARLY AND STEERED LEFT BEFORE THE CAR WAS BACKDOOR (LEFT) AND BACKSIDE (LEFT). TRIED TO POLISH

CARPARK ACCIDENT WITH CONCRETE PILLAR TOOK THE CORNER TO EARLY AND STEERED LEFT BEFORE THE CAR WAS FULLY CLEAR OF A CONCRETE PILLAR. SCRETCHKED THE BACKDOOR (LEFT) AND BACKSIDE (LEFT). TRIED TO POLISH THE SCRACTHES AWAY BUT IT IS STILL SLIGHTLY DENTED AND PAINT DAMAGED AND DOOR OPENER SCRATCHED. SO DECIDED THE CAR NEEDS A REPAIR.

# Are accident photos available for attachment? Yes Was there any video captured by Car Camera? No

ATTACHMENT(S)

### SKETCH PLAN

### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

### 5. Any false reporting may be referred to the Traffic Police Department for investigation.

- This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the
  report being made available aforesaid.

### 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time

Actual Driver's Signature (if driver is not the palicyholder)/ Date & Time

Witnessed by Reporting Centre Personnel

26/11/1401750

Sketch Plan



vJun2022

escr	ibe Circumstance of the Accident
	CAR PARK ACCIDENT WITH CONCRETE PILLAR
	TOOK THE CORNER TO EARLY AND STEERED LEFT
	BEFORE THE CAR WAS FULLY CLEAR OF A
	CONCRETE PILLAR, SCRETCHED THE BACKING
	(LEFT) AND BACKS DE (LEFT). TRIED TO
	POLISH THE SCRATCHES AWAY BUT IT IS
	STILL SCIGHTLY DENTED AND PAINT
	PAMAJED AND FOOR OPENER SCRATCHED.
	SO PECIDED THE CAR VEEDS A REPAIR
De	
7574550	claration e declare the foregoing particulars are true in every respect.
	an se
Poli	cyholder's Signature / Date & Time Actual Driver's Signature (if driver is not the policyholder) Witnessed by Reporting Centre Personnel (Name as in NRIC/IID card)
	20/11/290 1750

