

**AUTOBACS CAR CARE (SINGAPORE) PTE. LTD.**

8 Kaki Bukit Ave 4 #08-40/45/46 Premier@Kaki Bukit S(415875)
Tel : 6702 1555 Fax : 6702 1444
Co. Reg No. : 201500047H GST No. : 201500047H
Email : st.sim@autobacs.com.sg

TO	: INCOME INSURANCE (FBR7108J)	DATE	: 28-Nov-24
ATTENTION	: MOTOR CLAIMS DEPARTMENT	JOB TYPE	: T/P CLAIMS
OWNER PARTICULAR			
OWNER ID	: SXXXX289J	P -	
		S -	
		L -	
VEHICLE DETAILS			
VEHICLE NO.	: SMP3329U	TOTAL	:
MODEL / MAKE	: HYUNDAI AVANTE	L/S -20%	:
CHASSIS NO.	: KMHD841CMKU940385	SUB TOTAL	:
ACCIDENT DETAIL			
DATE	: 26-Nov-24		
TIME	: 17:40 HRS	CONTACT PERSON : MR. SIM 9844 0974	

QUOTATION SUMMARY PAGE 01**CLAIMS DETAIL : PARTS LIST**

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	F/L DOOR MIRROR ASSY	1	\$ 580.00	\$ 580.00
TOTAL PRICE				\$ 580.00
LESS -20%				\$ (116.00)
SUB TOTAL PRICE				\$ 464.00

QUOTATION SUMMARY PAGE 02**CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING**

TO LABOUR CHARGE FOR REMOVING F/L DOOR MIRROR ASSY OUT TO FACILITATE REPLACEMENT OF DAMAGED PART	\$ 300.00	100	
TO RESPRAY COMPLETE MIRROR ASSY	\$ 150.00	80	

TOTAL \$ 450.00

ESTIMATE REPORT

TOTAL PARTS COST	:	\$ 464.00
TOTAL LABOUR COST	:	\$ 450.00
TOTAL REPAIR COST	:	\$ 914.00

APPROVED DETAILS

NO. OF REPAIR DAYS	:	DAYS
REPAIR UNDER	:	PART BY PART OR LUMP SUM
DATE / TIME OF SURVEY	:	
SURVEYED BY / FROM	:	
CONTACT NUMBER	:	
EMAIL ADDRESS	:	
DATE / TIME OF RE-SURVEY	:	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

not about
his
p17 # 644
1 day
take photo before repair
28/11/24