

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT						
	INCOME INSURAN	ICE LTD		Ref:	CS/INC24110629/Aqh3m4(N)	
	75 BRAS BASAH FINCOME CENTRES	ROAD SINGAPORE 189557		Date:	06/02/2025	
	ATTN: JULIE			Code:	INC	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SNB 7626Y	Veh. Inspected	k	SNR 985Y	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	MT/1306073-002	Excess (\$)		0.00	
	Assign From	ANNIE KOH	Assign Date		29/11/2024	
2. Vehicle Particulars & Condition						
	Make & Model	MAZDA 3 4DR 1.5 AT M- HYBRID	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2024	
	Chassis No.	JM6BP2SAAR1202550	Colour		WHITE	
	Odometer	20900 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	205/60R16	YOKOHAMA		6 mm	
	L/H Front Tyre	205/60R16	YOKOHAMA		6 mm	
	R/H Rear Tyre	205/60R16	YOKOHAMA		6 mm	
	L/H Rear Tyre	205/60R16	YOKOHAMA		6 mm	
4. Description of Damages						
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.					
	DAMAGES SEE DETAILS.					
5. General Information						
	Accident Date	26/11/2024	Inspect Date /	Time	29/11/2024 ( 03:24 PM )	
	Survey held at	KT MOTORWERK	•			
		3012 BEDOK INDUSTRIAL PARK E, #01-2020, BEDOK INDUSTRIAL PARK E, SINGAPORE 489978				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORM	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				