

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT						
	INCOME INSURAN	ICE LTD		Ref:	CS/INC24120011/Anh3e2(N)	
	75 BRAS BASAH FINCOME CENTRE	ROAD SINGAPORE 189557		Date:	16/01/2025	
	ATTN: JULIE MAN	GUBAT		Code:	INC	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SLK 1622Z	Veh. Inspected	l	SNS 7222P	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	MT/1306557-001	Excess (\$)		0.00	
	Assign From	JULIE MANGUBAT	Assign Date		02/12/2024	
2. Vehicle Particulars & Condition						
	Make & Model	MERCEDES BENZ C180	c.c		1595	
	Engine No.	HIDDEN	Year of Reg.		2014	
	Chassis No.	WDD2050402R003673	Colour		WHITE	
	Odometer	154369 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	225/50 R17	CONTINENTAL		6 mm	
	L/H Front Tyre	225/50 R17	CONTINENTAL		6 mm	
	R/H Rear Tyre	225/50 R17	CONTINENTAL		6 mm	
	L/H Rear Tyre	225/50 R17	CONTINENTAL		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	27/11/2024	Inspect Date /	Time	04/12/2024 (01:18 PM)	
	Survey held at	ONE GARAGE PTE LTD	•			
		8 KAKI BUKIT AVENUE 4 #03-33 PREMIER @ KAKI BUKIT SINGAPORE 415875				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORI	MAL PERIOD FOR REPAIR:		3 Worki	ng Days	