

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

Annialed to redefation internationale des Experts En Adtoniobile						
	AUTO & GENERAL	L INSURANCE (S) PL	F	Ref:	CS/AGI24120015/Avp3e2(N)	
		INSURANCE) 16 RAFFLES NG LEONG BUILDING 81	С	Date:	16/06/2025	
	ATTN: CHEN HOV	I	C	Code:	AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SLU 225R	Veh. Inspected		SBP 6979D	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10033203/CH	Excess (\$)		0.00	
	Assign From	CHEN HOW	Assign Date		02/12/2024	
2. Vehicle Particulars & Condition						
	Make & Model	MERCEDES BENZ 200E	c.c		1996	
	Engine No.	HIDDEN	Year of Reg.		1991	
	Chassis No.	WDB1240212B330817	Colour		SILVER	
	Odometer	509372 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	205/55 R16	CONTINENTAL		6 mm	
	L/H Front Tyre	205/55 R16	CONTINENTAL		6 mm	
	R/H Rear Tyre	205/55 R16	CONTINENTAL		6 mm	
	L/H Rear Tyre	205/55 R16	CONTINENTAL		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	29/11/2024	Inspection Date		03/12/2024	
	Survey held at	2020 SPRAY PAINTING PTE LT	D			
		8 KAKI BUKIT AVENUE 4, #03-19, PREMIER @ KAKI BUKIT, SINGAPORE 415875				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days					