



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924 ATTN: ELAINE CHEONG			Ref: CS/AGI24120016/Enp3e2(N) Date: 24/01/2025 Code: AGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SDZ 7689H	Veh. Inspected	SNQ 1151K	
Policy No.	P11113190R00	Coverage (\$)	0.00	
Claim No.	C10033156/EC	Excess (\$)	0.00	
Assign From	ELAINE CHEONG	Assign Date	02/12/2024	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI SX2 KONA	c.c	1580	
Engine No.	HIDDEN	Year of Reg.	2024	
Chassis No.	KMHHB811VRU044155	Colour	GREY	
Odometer	71992 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/65 R16	KUMHO	6 mm	
L/H Front Tyre	205/65 R16	KUMHO	6 mm	
R/H Rear Tyre	205/65 R16	KUMHO	6 mm	
L/H Rear Tyre	205/65 R16	KUMHO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/11/2024	Inspection Date	02/12/2024	
Survey held at	MY CAR CONSULTANT PTE LTD 60 JALAN LAM HUAT #05-21 CARROS CENTRE SINGAPORE 737869			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		