

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | | |
|--|--|--|----------------|-----------------------|--|
| MS | LONPAC INSURANC | E BHD | Ref: | CS/LPC24060309/Uvh3e2 | |
| | 300 BEACH ROAD | | Date: | 30/07/2024 | |
| | #17-04/07 THE CON | COURSE SINGAPORE 199555 | Code: | LPC2 | |
| 1. | Policy Particulars :- T | | | | |
| ١. | Insured Veh. | XD 1061L | Veh. Inspected | XE 2068G | |
| | Policy No. | AD TOOTE | Coverage | 0 | |
| | Claim No. | 23/24/24/VC05/029433 | Excess | \$0.00 | |
| | Assign From | CHARMAINE KONG | Assign Date | 28/06/2024 | |
| 2. | Assign From | Vehicle | | 20/00/2024 | |
| | Make & Model | SCANIA P360 | C.C | 12742 | |
| | Engine No. | 6939301 | Year of Reg. | 15/08/2016 | |
| | Chassis No. | YS2P6X40005423546 | Colour | WHITE | |
| | Odometer | 143323 KM | Steering | IN ORDER | |
| | Brakes | IN ORDER | General | GOOD | |
| | Modification(s) | RIMS: NIL | General | GOOD | |
| | | | | | |
| 3. | | | | | |
| | D#15 4.7 | Size 295/80R22.5 | Make GITI | Balance (mm) | |
| | R/H Front Tyre | 295/80R22.5 295/80R22.5 | GITI | 6 | |
| | L/H Front Tyre | 295/80R22.5 (D/D) | GITI | 6/6/6/6 | |
| | R/H Rear Tyre | 295/80R22.5 (D/D) 295/80R22.5 (D/D) | GITI | 6/6/6/6 | |
| _ | L/H Rear Tyre | () | | 6/6/6/6 | |
| 4. | Description of Damages E VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. | | | | |
| DAMAGES SEE DETAILS. | | | | | |
| 5 . | | | | | |
| <u> </u> | Accident Date 24/06/2024 Inspection Date 02/07/2024 | | | | |
| | Survey held at HUP LIAN HUAT ENGINEERING WORKS - 38 DEFU LANE 9, DEFU INDUSTRIAL ESTATE, | | | *=- * · · · = * = · | |
| | SINGAPORE 539278 | | | | |
| 5a. Remarks | | | | | |
| A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | | |
| 5b. | | | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days | | | | | |
| Letting the result of the resu | | | | | |