



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24120018/Dnh3e2
75 BRAS BASAH ROAD	Date:	16/12/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMV 2088P	Veh. Inspected	SLZ 6633E
Policy No.	-	Coverage	0
Claim No.	MT/1306314-003	Excess	\$0.00
Assign From	RAJESWARY	Assign Date	02/12/2024

2. Vehicle Details

Make & Model	MERCEDES BENZ C200	C.C	1991
Engine No.	27492030430087	Year of Reg.	05/01/2016
Chassis No.	WDD2050422R092824	Colour	BLACK
Odometer	116649 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	255/35R19	MICHELIN	5
L/H Front Tyre	255/35R19	MICHELIN	5
R/H Rear Tyre	255/35R19	MICHELIN	5
L/H Rear Tyre	255/35R19	MICHELIN	5

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. FRONT O/S AND REAR O/S UNDERCARRIGE AFFECTED.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	27/11/2024	Inspection Date	03/12/2024 (10:37)
Survey held at	ALFRED AUTO SERVICES & SUPPLIES BLK 5035 ANG MO KIO 3 #01-355 ANG MO KIO INDUSTRIAL PARK 2 SINGAPORE 569538		

5a.	Remarks
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.	

5b.	Estimate Days of Repair
ESTIMATED NORMAL PERIOD FOR REPAIR: 9 Working Days	