Asst. Sign: REF: CS/INC24120027/Avh3

ASSIGNMENT

From: Date:

Estm Cost:

OD / PD / TP RES / CD RES / EVA / INV / MV

To insp Vehicle No:

at W/O Wksp m/s

of

Insured: SJE 2423E

Policy No

Claims No. MT/1306790-001

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Veh No: SLG9899K Yr Regn: 2016 / Aug'st.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Volkswagen Jetta c.c 1390

Colour Blue. A/C: Insured / Std / NI / NA

Sp.Reading 243468 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WVW2221626M005255

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55 R16.

R: 205/55R16.

	N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	06 mm	R/Bal.	06 mm
L/Bal.	06 mm	L/Bal.	06 mm

D.O.A. 29/11/2024 D.O.I. 03/12/24.

Survey held at JL Perfect.

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP INC. COE Expiry :
20/2/25	Adrian confirmed LS $6200 (Red 37,078.68, 85%)
	Estimate given during : Yes (✓)
	MV : 301C 1st Survey : No ( )
	PV : 189C
	Nett : 111C
	9927

Date/Time, File Pass to? 1)

Date/Time, File Return to? 2)

Report Format : ☐ : Preli. Report ☐ : Final Report

Days Of Repair: 6

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($) ☐ : Interview ($) ☐ : Tech. Inve ($)

Survey Fee:	
Transportation:	
$3 + R$8 = $11	
Photos	
Others	