

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Est: \_\_\_\_\_  
 OD / TP RES / CD RES / EVA / INV / MV  
 To in Vehicle No: \_\_\_\_\_  
 at W/O \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claim No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Val: \_\_\_\_\_

(Policy Condition)

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Remarks: The vehicle had commenced its repair at the time of inspection.

Bel. or Market Value: \_\_\_\_\_

IDAC Accident Report \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SL69899K Yr Regn: 2016 / Aqnt.

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volkswagen Jetta C.D. 1380

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 243468 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WVW 222162GM005255

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55 R16

R: 205/55 R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. \_\_\_\_\_ D.O.I. 03/12/24

Survey held at JL Perfect

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP INC

COE Expiry: \_\_\_\_\_

Estimate given during: Yes ☒ No ☐

1st Survey: Yes ☒ No ☐

MV: 301K

PV: 189K

Nett: 11.1K

992K

Date/Time, File Pass to?

☐

: Preli. Report

Days Of Repair: \_\_\_\_\_

1)

☐

: Final Report

Resurvey No. of Trip: \_\_\_\_\_

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$ \_\_\_\_\_)

☐

: Interview (\$ \_\_\_\_\_)

☐

: Tech. Invt (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

B + R8. \$1

Photos

Others

Report Format: \_\_\_\_\_

Report Form / L.P.P. / C