

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT						
	INCOME INSURAN	ICE LTD		Ref:	CS/INC24120030/Aqh3m4(N)	
	75 BRAS BASAH R INCOME CENTRES	ROAD SINGAPORE 189557		Date:	24/01/2025	
	ATTN: HELENA TA	۱N		Code:	INC	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	CB 7816X	Veh. Inspected	k	SNN 5335L	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	MT/1306718-002	Excess (\$)		0.00	
	Assign From	HAZALYSA BINTE IBRAHIM	Assign Date		03/12/2024	
2. Vehicle Particulars & Condition						
	Make & Model	HONDA VEZEL	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2023	
	Chassis No.	RV31013977	Colour		GREY	
	Odometer	26141 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	215/60R16	DUNLOP		6 mm	
	L/H Front Tyre	215/60R16	DUNLOP		6 mm	
	R/H Rear Tyre	215/60R16	DUNLOP		6 mm	
	L/H Rear Tyre	215/60R16	DUNLOP		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND UNDERCARRIAGE.					
	DAMAGES SEE DE	ETAILS.			y*	
5.	_					
	Accident Date	30/11/2024	Inspect Date /	Time	03/12/2024 (01:51 PM)	
	Survey held at	N-51 AUTOMOTIVE PTE LTD				
		2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921				
5a.	5a. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORM	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				