

ASSIGNMENT

From: _____ Date: _____
 Est: _____
 OD / TP RES / OD RES / EVA / INV / MV
 To in _____ Vehicle No: _____
 at _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Vehicle: _____
 (Policy Condition)

Remark: The vehicle had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Report _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: JVV8785 Yr Regn: 2022, Dec
 Type: M.Car M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Mazda CX8 C.D. 2488
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: 38787 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: PP1KG A331 PM300380
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 225/55R19
 R: 225/55R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front	Rear
R/Bal. <u>06</u> mm	R/Bal. <u>06</u> mm
L/Bal. <u>06</u> mm	L/Bal. <u>06</u> mm
D.O.A. _____	D.O.A. <u>03/12/24</u>

Survey held at NSI

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP INC</u>
	<u>COE Expiry</u>
	<u>Estimate given during 1st Survey</u>
	<u>Yes (✓)</u>
	<u>No ()</u>
	<u>MV</u>
	<u>PV</u>
	<u>Nett</u>

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invoice (\$ _____)

Photos

Others

Report Format: _____

Report Date: _____



SIJIL PEMILIKAN KENDERAAN

JABATAN PENGANGKUTAN JALAN

DTKBWH10

No. Pendaftaran : JVV8785
No. ID : 871110235606
Nama Pemunya Berdaftar : JUI YU TING
Alamat : NO 6 JALAN EKOFLORA 5/24 TAMAN EKOFLORA
81100 JOHOR BAHRU JOHOR
No. Chasis/No. Enjin : PP1KGA331PM300380 / PY10857927
Buatan>Nama Model : MAZDA / CX-8 2.5G 2WD HIGH PLUS
Keupayaan Enjin : 2488
Bahan Bakar : PETROL
Status Asal : PEMASANGAN TEMPATAN
Kelas Kegunaan : PSDN-JIP/VAN/BAS/KVN IND
Jenis Badan/Tahun Dibuat : JIP / 2022
Tarikh Pendaftaran : 29/12/2022
B. D. M/B. G. K/BTM : -
Syarat Pendaftaran 1 : -
Syarat Pendaftaran 2 : -
Syarat Pendaftaran 3 : -



LESEN KENDERAAN MOTOR

AKTA PENGANGKUTAN JALAN 1987 KAEDAH KENDERAAN MOTOR (PENDAFTARAN DAN PELESENAN) 1959

Sila baca maklumat di muka sebelah sebelum
melekatkan LKM ini di cermin kenderaan anda

2023
JVV8785
28 Dis
0101181 eJwS1M 29122022
VELO2006 093682 IZZWAN
SEMENANJUNG
29122022 28122023
2488SP AD RM800.40
PERSENDIRIAN



LESEN KENDERAAN MOTOR

AKTA PENGANGKUTAN JALAN 1987 KAEDAH KENDERAAN
MOTOR (PENDAFTARAN DAN PELESENAN) 1959

124662724



eJwS1M

Layarilah portal JP

gov.my