



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

Ref: CS/INC24120034/Enh3e2(N)

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

Date: 14/01/2025

ATTN: CHARLOTTE CHEW

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBE 4251R	Veh. Inspected	GBC 351Y
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1306608-001	Excess (\$)	0.00
Assign From	CHARLOTTE CHEW	Assign Date	03/12/2024

2. Vehicle Particulars & Condition

Make & Model	NISSAN NV200	c.c	1461
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	JN1YBAM20U0003133	Colour	SILVER
Odometer	262514 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	175/70 R14	TRIANGLE	5 mm
L/H Front Tyre	175/70 R14	TRIANGLE	5 mm
R/H Rear Tyre	175/70 R14	TRIANGLE	5 mm
L/H Rear Tyre	175/70 R14	TRIANGLE	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	30/10/2024	Inspect Date / Time	03/12/2024 (10:52 AM)
Survey held at	10 KAKI BUKIT AVE 2 #01-19, KAKI BUKIT AUTOHUB, SI		
Repairer	AB ENGINEERING PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days