

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

16g. 16. 166667 1661 16 6667 166 17					
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Ref:	CS/AGI24120040/Avh3m4(N)	
		INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Date	e: 11/03/2025	
	ATTN: CHEN HOV	V	Cod	e: AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMS 6413Z	Veh. Inspected	SNH 669M	
	Policy No.	P10702213R02	Coverage (\$)	0.00	
	Claim No.	C10033210/CH	Excess (\$)	0.00	
	Assign From	LAN BOON CHIN	Assign Date	03/12/2024	
2. Vehicle Particulars & Condition					
	Make & Model	HONDA VEZEL	c.c	1496	
	Engine No.	HIDDEN	Year of Reg.	2022	
	Chassis No.	RV31003708	Colour	WHITE	
	Odometer	77421 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	215/55R16	YOKOHAMA	6 mm	
	L/H Front Tyre	215/55R16	YOKOHAMA	6 mm	
	R/H Rear Tyre	215/55R16	YOKOHAMA	6 mm	
	L/H Rear Tyre	215/55R16	YOKOHAMA	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	30/11/2024	Inspection Date	02/12/2024	
	Survey held at	Survey held at KT MOTORWERK			
		3012 BEDOK INDUSTRIAL PARK E, #01-2020, BEDOK INDUSTRIAL PARK E, SINGAPORE 489978			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	D. Estimate Days of Repair				

6 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: