



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS AUTO & GENERAL INSURANCE (S) PL Ref: CS/AGI24120045/Uvh3m4  
(BUDGET DIRECT INSURANCE) Date: 13/12/2024  
190 CLEMENCEAU AVENUE #03-01  
SINGAPORE SHOPPING CENTRE SINGAPORE 239924 Code: AGI

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGL 9882R	Veh. Inspected	SMC 6388Y
Policy No.	-	Coverage	0
Claim No.	C10033247/CY	Excess	\$0.00
Assign From	LAN BOON CHIN	Assign Date	03/12/2024

### 2. Vehicle Details

Make & Model	NISSAN X-TRAIL 2.0 CVT	C.C	1997
Engine No.	MR20334001C	Year of Reg.	13/07/2018
Chassis No.	JN1JANT32Z0011322	Colour	GREY
Odometer	114389 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	225/55R19	YOKOHAMA	6
L/H Front Tyre	225/55R19	YOKOHAMA	6
R/H Rear Tyre	225/55R19	YOKOHAMA	6
L/H Rear Tyre	225/55R19	YOKOHAMA	6

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	26/11/2024	Inspection Date	03/12/2024
Survey held at	T K LEE AUTOMOTIVE PTE LTD NO. 1 KAKI BUKIT AVE 6 #02-47 AUTOBAY SINGAPORE 417883		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days