



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

ATTN: RAJESWARY

Ref: CS/INC24120056/Anh3m4(N)

Date: 11/03/2025

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBN 5255B	Veh. Inspected	GBM 2791U
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1306968-001	Excess (\$)	0.00
Assign From	HAZALYSA BINTE IBRAHIM	Assign Date	04/12/2024

2. Vehicle Particulars & Condition

Make & Model	CITROEN E-BERLINGO	c.c	0
Engine No.	HIDDEN	Year of Reg.	2023
Chassis No.	VR7EAKXZJ863075	Colour	BLUE
Odometer	54459 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/65R16	MICHELIN	6 mm
L/H Front Tyre	215/65R16	MICHELIN	6 mm
R/H Rear Tyre	215/65R16	MICHELIN	6 mm
L/H Rear Tyre	215/65R16	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	02/12/2024	Inspect Date / Time	04/12/2024 (02:57 PM)
Survey held at	HUA MENG SPRAY PAINTING WORKSHOP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 8 Working Days