

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile   |   |                             |                |                     |  |  |
|---|---|-----------------------------|----------------|---------------------|--|--|
| MS  | INCOME INSURAN  | CE LTD                      | Ref:           | CS/INC24070003/Avh3 |  |  |
|   | 75 BRAS BASAH ROAD<br>INCOME CENTRE SINGAPORE 189557  |                             | Date:          | 30/09/2024          |  |  |
|   | INCOME CENTRES  | SINGAPORE 189557            | Code:          | INC                 |  |  |
| 1.  | Policy Particulars :- THIRD PARTY CLAIM   |                             |                |                     |  |  |
|   | Insured Veh.  | YN 8313A                    | Veh. Inspected | SLV 8209E           |  |  |
|   | Policy No.  | -                           | Coverage       | 0                   |  |  |
|   | Claim No.   | MT/1284095-002              | Excess         | \$0.00              |  |  |
|   | Assign From   | ENG HUEY HUEY               | Assign Date    | 01/07/2024          |  |  |
| 2. Vehicle Details  |   |                             |                |                     |  |  |
|   | Make & Model  | MITSUBISHI ATTRAGE          | C.C            | 1193                |  |  |
|   | Engine No.  | 3A92UGP4496                 | Year of Reg.   | 17/01/2018          |  |  |
|   | Chassis No.   | MMBSTA13AJH001078           | Colour         | RED                 |  |  |
|   | Odometer  | 60379 KM                    | Steering       | IN ORDER            |  |  |
|   | Brakes  | IN ORDER                    | General        | GOOD                |  |  |
|   | Modification(s)   | RIMS: SPORTS RIM            |                |                     |  |  |
| 3. Conditions of Tyres  |   |                             |                |                     |  |  |
|   |   | Size                        | Make           | Balance (mm)        |  |  |
|   | R/H Front Tyre  | 185/55R15                   | YOKOHAMA       | 6                   |  |  |
|   | L/H Front Tyre  | 185/55R15                   | YOKOHAMA       | 6                   |  |  |
|   | R/H Rear Tyre   | 185/55R15                   | YOKOHAMA       | 6                   |  |  |
|   | L/H Rear Tyre   | 185/55R15                   | YOKOHAMA       | 6                   |  |  |
| 4. Description of Damages   |   |                             |                |                     |  |  |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  |   |                             |                |                     |  |  |
| DAMAGES SEE DETAILS.  |   |                             |                |                     |  |  |
| 5.  | General Information   |                             |                |                     |  |  |
|   | Accident Date 28/06/2024 Inspection Date 01/07/2024 (14:00)   |                             |                |                     |  |  |
|   | Survey held at JL PERFECT AUTOWORK PTE LTD<br>8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875 |                             |                |                     |  |  |
| 5a.   | Remarks   |                             |                |                     |  |  |
| A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |   |                             |                |                     |  |  |
| 5b  |   | 5b. Estimate Days of Repair |                |                     |  |  |

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days