



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24120061/Kqh3e2
16 RAFFLES QUAY	Date:	12/12/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SH 7169J	Veh. Inspected	SLB 5197E
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24010570MFCT	Excess	\$0.00
Assign From	TEO SWEE KEONG	Assign Date	04/12/2024

2. Vehicle Details

Make & Model	FORD FOCUS (A)	C.C	1596
Engine No.	FY86721	Year of Reg.	12/04/2016
Chassis No.	WF05XXGCC5FY86721	Colour	RED
Odometer	131018 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: STANDARD ALLOY RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	205/55R16	NEXEN	9
L/H Front Tyre	205/55R16	NEXEN	9
R/H Rear Tyre	205/55R16	NEXEN	9
L/H Rear Tyre	205/55R16	NEXEN	9

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	30/11/2024	Inspection Date	05/12/2024
Survey held at	CARWORKZ - BLK 10 SIN MING INDUSTRIAL ESTATE SECTOR C #01-22 SINGAPORE 575645		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days