

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS		INSURANCE (S) PL	Ref:	CS/AGI24120062/Kqh3m4
	(BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01		Date:	13/12/2024
		PPING CENTRE SINGAPORE 239924	Code:	AGI
1.	Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	SDA 8188L	Veh. Inspected	SMK 2817K
	Policy No.	-	Coverage	0
	Claim No.	C10033176/EC	Excess	\$0.00
	Assign From	FRAULEINE KHOO	Assign Date	04/12/2024
2.	2. Vehicle Details			
	Make & Model	HONDA ODYSSEY (A)	C.C	2356
	Engine No.	K24W72460800	Year of Reg.	01/04/2019
	Chassis No.	JHMRC1880KC201126	Colour	METALLIC PEARL WHITE
	Odometer	91840 KM	Steering	IN ORDER
	Brakes	IN ORDER	General	GOOD
	Modification(s)	RIMS: STANDARD ALLOY RIM		
3. Conditions of Tyres				
		Size	Make	Balance (mm)
	R/H Front Tyre	215/55R17	YOKOHAMA	9
	L/H Front Tyre	215/55R17	YOKOHAMA	9
	R/H Rear Tyre	215/55R17	YOKOHAMA	9
	L/H Rear Tyre	215/55R17	YOKOHAMA	9
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.				
DAMAGES SEE DETAILS.				
5.	General Information			
	Accident Date	29/11/2024	Inspection Date	05/12/2024
	Survey held at	THIAM HENG HUAT PTE LTD 176 SIN MING DRIVE		
		#05-14 SINGAPORE 575721		
5a.	. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
·				

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days