

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	LIBERTY INSURAN	CE PTE LTD	Ref:	CS/LIP24070004/Uqh3	
		AY #25-01 NORTH TOWER 33	Date:	01/07/2024	
	SINGAPORE 04858		Code:	LIP	
1.		Policy Particulars :- T	HIRD PARTY CLA	IM	
	Insured Veh.	GBJ 9695J	Veh. Inspected	SMR 7375Z	
	Policy No.	-	Coverage	0	
	Claim No.	IVS24/1240	Excess	\$0.00	
	Assign From	ANDY SEAH	Assign Date	28/06/2024	
2. Vehicle Details					
	Make & Model	TOYOTA VOXY HYBRID (A)	C.C	1797	
	Engine No.	2ZR0E70175	Year of Reg.	20/01/2020	
	Chassis No.	ZWR800415249	Colour	BLACK	
	Odometer	121670 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres					
		Size	Make	Balance (mm)	
	R/H Front Tyre	195/65R15	GITI	6	
	L/H Front Tyre	195/65R15	GITI	6	
	R/H Rear Tyre	195/65R15	GITI	6	
	R/H Rear Tyre L/H Rear Tyre	195/65R15 195/65R15	GITI GITI	6	
4.	L/H Rear Tyre	195/65R15  Description of	GITI of Damages		
	L/H Rear Tyre	195/65R15	GITI of Damages		
THE	L/H Rear Tyre	195/65R15  Description of the DAMAGES AT THE FRONT PORTION OF THE PROPERTY OF	GITI of Damages		
THE	L/H Rear Tyre  VEHICLE SUSTAIN	195/65R15  Description of the DAMAGES AT THE FRONT PORTION OF THE PROPERTY OF	GITI of Damages ON.		
THE	L/H Rear Tyre  VEHICLE SUSTAIN	195/65R15  Description of the DAMAGES AT THE FRONT PORTIONS.	GITI of Damages ON.		
THE	L/H Rear Tyre  VEHICLE SUSTAIN  MAGES SEE DETAILS	195/65R15  Description of the properties of the	GITI of Damages ON. formation Inspection Date	01/07/2024	
THE	L/H Rear Tyre  VEHICLE SUSTAIN  AGES SEE DETAILS  Accident Date	195/65R15  Description of ED DAMAGES AT THE FRONT PORTIONS.  General Integral 26/06/2024	GITI of Damages ON. formation Inspection Date	01/07/2024	
THE DAM  5.  5a. A) T	L/H Rear Tyre  VEHICLE SUSTAIN  AGES SEE DETAILS  Accident Date  Survey held at  HE INSPECTION WA	195/65R15  Description of ED DAMAGES AT THE FRONT PORTIONS.  General Info 26/06/2024  1 KAKI BUKIT AVENU 6, AUTO BAY@	GITI  of Damages  ON.  formation  Inspection Date  KAKI BUKI #01-04  arks  EJUDICE" BASIS.	01/07/2024 REPAIRER: KT GARAGE PTE LTD	
THE DAM  5.  5a. A) T	L/H Rear Tyre  VEHICLE SUSTAIN  AGES SEE DETAILS  Accident Date  Survey held at  HE INSPECTION WA	Description of ED DAMAGES AT THE FRONT PORTIONS.  General Interpretation of the Company of the C	GITI of Damages ON. formation Inspection Date OR KAKI BUKI #01-04 arks EJUDICE" BASIS. OT AUTHORISED F	01/07/2024 REPAIRER: KT GARAGE PTE LTD	