



**SINGAPORE
POLICE FORCE**



T/20241202/2063

Police Station Of Origin:
Clementi N.P.C
6 Lempeng Drive SINGAPORE 128496
Tel No: 1800-8729999

1 of 3

Report No. T/20241202/2063

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 02/12/2024 16:23		Vide Report No.:		Station Diary No.: 47	
Informant's Particulars					
Name of Informant: GAO TIANSHUO			Address:		
ID Type / ID No.: FIN NO /			Contact No.: Home/Office: Mobile:		
Nationality: CHINESE			Email:		
Sex: Male	Age:	Date of Birth:	Type of Informant: Driver		
Race: Chinese			Language:		
Occupation: Lorry Driver			Driving Licence Information: Class: 3,4 Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 29/11/2024 10:35	Type of Location: Straight Road
Location: WOODLANDS AVENUE 3				
Weather: Drizzling		Road Surface: Wet		
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Conditio	No of Passenger
SMB1639L (Not Accurate)	Bus (Passenger)					0
XD553R	Garbage/Sanit ary Wagon				Slightly Damaged	0



**SINGAPORE
POLICE FORCE**



T/20241202/2063

Police Station Of Origin:
Clementi N.P.C
6 Lempeng Drive SINGAPORE 128496
Tel No: 1800-8729999

2 of 3

Report No. T/20241202/2063

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	GAO TIANSHUO	ID No.	
Related Vehicle	XD553R (Garbage/Sanitary Wagon)	Contact No.	
Hospital/Clinic	NIL	Class of Driving Licence & Expiry	Class: 3,4 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of	NIL

Brief Details.

On 29/11/2024, at about 1038hrs, I was driving my vehicle with plate number XD553R along lane 2 of Woodlands Ave 3 from Krangi MRT station towards Marsiling MRT station direction. Short distance after the T-junction of Woodlands Road and Woodlands Ave 3, a green colour single deck bus with plate number SMB1639L approached from the 3rd land, entered my lane and side swipe my vehicle, causing my left side mirror to detached and damaged my front bumper. The bus did not stop, I turned into woodlands Industrial Park D Street 1 and make a check on my vehicle and realised the damaged stated above.



**SINGAPORE
POLICE FORCE**



T/20241202/2063

Police Station Of Origin:
Clementi N.P.C
6 Lempeng Drive SINGAPORE 128496
Tel No: 1800-8729999

3 of 3

Report No. T/20241202/2063

CONTINUATION OF REPORT

Signature of Officer Recording The
D /
SCSGT(1) TANG HONG QIAN

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / HRT /
INSP (1) KASMAWATI BTE SAMIAN
Contact No.: 65476368

Signature Of Informant:

Date/Time:
02/12/2024 16:23

Classification Of Case:

NP168