

(08/11/13) wef

ASS. REC. BY: Marius

REF:

CS/ICS 24/20080/UGH3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLF 355C

at Workshop m/s 200M

of _____

Insured: SND/3143

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 828k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

716k

Vehicle: IN / OUT

Date: _____ Person Contacted: LTA 916669

Veh No: SLF 355C Yr Regn: 11/08/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CAI

Make: Mazda 3 c.c. 1496

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: 156844 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: Jm6Bm44A8G0343022

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim or

Tyre Size: F: 225/45-R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front: 6 mm Rear: 6 mm

R/Bal. _____ mm R/Bal. _____ mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 04/12/24 D.O.I. 6/12/24

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction Repair

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

____ \$ + RS. ____ \$

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I.: (\$ _____)

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	716F
Vehicle Details	
Vehicle No.:	SLF355C
Vehicle to be Exported:	No
Intended Deregistration Date:	06 Dec 2024
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 5-DOOR HATCHBACK 1.5L SP.6EAT
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	P520368751
Chassis No.:	JM6BM44A8G0343022
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$19,298.00
Original Registration Date:	11 Aug 2016
First Registration Date:	11 Aug 2016
Transfer Count:	2
Actual ARF Paid:	\$14,298.00 1.4%
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Aug 2026
PARF Rebate Amount:	\$7,863.00
Intended COE Rebate Details	
COE Expiry Date:	10 Aug 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$52,503.00
COE Rebate Amount:	\$8,806.00
Total Rebate Amount:	\$16,669.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 06 Dec 2024

OK

