

MOTOR SURVEY ASSIGNMENT

Date	03/12/2024	Our Ref No.	D24010534MFCT
Accident Date	30-11-2024	Claim Type	Third Party
Insured Vehicle	SHA7807T	Third Party Vehicle	SLW6319D
Survey Location	CHENG HOE MOTOR PTE LTD BLK 1019 YISHUN IND. PARK A #01-374 (S) 768761	Contact Person	Dorlyn Li / June
Contact No.	67556142	Fax No.	

Survey Type Without Prejudice - Please submit estimate and video

Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person		Fax No. 68416315
Contact Number	62563561	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

Encl. Accident Reports

Cc : Workshop	CHENG HOE MOTOR PTE LTD	Attention	Dorlyn Li / June
Officer Incharge	JASONTEA		

IMPORTANT NOTE

Kindly submit the survey report by **email only** to surveyor@msfirstcapital.com.sg within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.