

ASS. REC. BY:

REF: 1051

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / R/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech Invs (\$)

☐

: Weekend (\$)

S - RS. SI

: Fines

: Others

TOTAL

Report Format:

Lump Sum / I.B.I. (\$) 1

Not Authored
Mercury B4 paint
7day,



ESTIMATE TO REPAIR

VEHICLE NO. : SNR 6832 R
MAKE : HYUNDAI
MODEL : SX2 KONA 1.6 GDI HEV
YEAR : 2024
CHASSIS NO : KMH8B811VRU071103

SURVEYOR NAME :
DATE OF SURVEY :
TIME OF SURVEY :

DATE : 06-Dec-24
DATE OF ACCIDENT : 28-Nov-24
THIRD PARTY REF : SFB 1819 S / ECICS

No.	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	rear bumper			De form m3 cm \$ 1,015.00	1,015.00
1 pc	rear bumper lower diffuser			\$ 856.70	856.70
1 pc	rear bumper rh lamp			\$ 953.00	953.00
1 pc	rear bumper rh retainer			\$ cm 32.00	32.00
1 pc	rear bumper rh cover			\$ cm 201.00	201.00
1 pc	rear rh fender undershield			\$ Div 275.00	275.00
1 pc	rear rh fender arch garnish			\$ 473.00	473.00
1 pc	rear rh radar			\$ 1,568.00	1,568.00
1 pc	rear rh door			\$ Rh 2,063.00	2,063.00
1 pc	rear rh door frame tape			\$ na 55.00	55.00
1 pc	rear rh door protector			\$ wt 485.00	485.00
1 pc	rear rh door regulator			\$ 277.00	277.00
1 pc	rear rh door power window Motor			\$ 370.00	370.00
1 pc	rear rh door channel			\$ 241.00	241.00
1 pc	rear rh door rubber			\$ 171.00	171.00
1 pc	rear rh door check			\$ 50.00	50.00
2 ps	rear rh door hinges		\$ 120.00	\$ Rh 240.00	240.00
1 pc	front rh door			\$ Rh 1,789.00	1,789.00
1 pc	front rh door protector			\$ na 485.00	485.00
1 pc	front rh door lock			\$ na 398.00	398.00
1 pc	front rh door frame tape			\$ na 85.00	85.00
1 pc	front rh rubber			\$ 153.00	153.00
1 pc	front rh door regulator			\$ 283.00	283.00
1 pc	front rh door power window motor			\$ 370.00	370.00
1 pc	front rh door channel			\$ Rh 241.00	241.00
1 pc	rh side skirt			\$ 600.00	600.00
1 pc	front rh fender arch garnish			\$ wt 473.00	473.00
1 pc	front rh fender under-shield			\$ Rh 163.00	163.00
1 pc	front bumper			\$ n pin m3 cm 726.00	726.00
1 pc	front bumper lower			\$ wt 1,100.00	1,100.00
1 pc	front bumper rh lamp			\$ wt 2,216.00	2,216.00
1 pc	front bumper rh retainer			\$ Div 25.00	25.00
2 ps	rim		\$ 883.00	\$ 1,766.00	1,766.00
1 pc	front rh knuckle arm			\$ 518.00	518.00
1 pc	front rh lower arm			\$ 808.00	808.00
1 pc	front rh lower arm ??			\$ 107.00	107.00
1 pc	front rh shock absorber			\$ 490.00	490.00
	Balance C/F				\$ 22,121.70

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721
Tel:65-64520893 Fax:65-64589127 Email: edmund@LTM.sg Website : www.LTM.sg
Co.Reg No.199307277D GST Reg No.M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd

	Balance B/F				\$ 22,121.70
1 pc	front stabilizer bar				\$ 383.00 X
1 pc	front steering link				\$ 143.00 X
1 pc	front wheel bearing hub				\$ 721.00 7
	Less 20%				\$ 23,368.70
					\$ 4,673.74
					\$ 18,694.96
	To putty and spray paint.				\$ 1,800.00 1000
	towing				\$ 100.00 60
	to transfer door fitting				\$ 100.00 ✓
	to replace front under carriage				\$ 350.00 7
	to check wheel alignment				\$ 800.00 1200
	to anti rust				\$ 150.00 60
	labour charges				\$ 1,600.00 800
TG-BN/-	Total				\$ 23,594.96

KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Date:

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721

Tel:65-64520893 Fax:65-64589127

Email: edmund@LTM.sg

Website : www.LTM.sg

Co.Reg No.199307277D

GST Reg No.M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of First Submission 29/11/2024 11:17 (SGT)
Reported by Actual Driver
Date of Accident 28/11/2024 10:30 (SGT)
Exact Location of Accident 671 Yishun Street 72, Singapore
Additional Location Information -
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SNR6832R

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner LUMENS PTE LTD
Company Reg No 2XXXXX961K
Email Address accident@lumens.sg
Mobile Phone No (Phone) +65-87781765
Alternative Phone No (Office) +65-87781765

VEHICLE PARTICULARS

Manufacturer Hyundai
Model SX2 KONA 1.6 GDI HEV
Variant -
Exact purpose for which vehicle was being used at time of accident Private hire
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private hire
Transmission Auto
CC 1580
Vehicle Fuel Petrol-Electric
First Registration Date -
Chassis no KMHBB811VRU071103
Effective Date/Time of Ownership -

INSURANCE COMPANY

Name of Insurance Company Tokio Marine Insurance Singapore Ltd
Policy Number / Cover Note Number 24-MAB00576-R00

DRIVER

Name of Driver	MOHAMMAD ASIEK BIN ASHARI
NRIC No	SXXXX121E
Date Of Birth	05/08/1979
Occupation	Outdoor
Driving Pass Date	27/06/2003
Driving License Pass Class	3
Driving License Validity	Valid
Driving experience	21 YEARS AND 5 MONTHS
Gender	Male
Mobile Number	(Phone) +65-88261469
Alt. Phone Number	-
Email Address	accident@lumens.sg
Address	760 YISHUN ST 72 #02-316
Address complement	-
Postcode	760760
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Change/cross lane
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

ON 28/11/2024 ABOUT 1030HRS I WAS DRIVING VEHICLE A BEARING REGISTRATION NUMBER SNR6832R ENROUTING OUT FROM MY HOUSE CARPARK TO START WORK. WHILE DRIVING ALONG BLK 761 YISHUN ST 72 OPEN CARPARK, VEHICLE B BEARING REGISTRATION NUMBER SFB1819S CAME OUT FROM HIS LOT AND HIT ON MY RIGHT SIDE OF VEHICLE A. NOBODY WAS INJURED DURING THIS INCIDENT.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Apply for PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Owner ID:

Company

Vehicle Details

961K

Vehicle No.:

Vehicle to be Exported:

SNR6832R

Intended Deregistration Date:

Yes

Vehicle Make:

06 Dec 2024

Vehicle Model:

HYUNDAI

Primary Colour:

SX2 KONA 1.6 GDI HEV

Manufacturing Year:

White

Engine No.:

2024

Chassis No.:

G4LLRU430133

Maximum Power Output:

KMH811VRU071103

Open Market Value:

96.0 kW (128 bhp)

Original Registration Date:

\$25,453.00

First Registration Date:

28 Jun 2024

Transfer Count:

28 Jun 2024

Actual ARF Paid:

0

Intended PARF Rebate Details

\$22,635.00

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

27 Jun 2034

PARF Rebate Amount:

\$16,976.00

Intended COE Rebate Details

COE Expiry Date:

27 Jun 2034

COE Category:

A - Car-Details at OneMotoring

COE Period(Years):

10

QP Paid:

\$88,200.00

COE Rebate Amount:

\$70,560.00

Total Rebate Amount:

\$87,536.00

Message

You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.
The information contained herein is correct as at 06 Dec 2024

OK