

Our Job Ref No : 305532929
Date : 15.10.2022ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156**FINALIZATION FORM**To : LKK
Attn : GUO QIANG



Fax :

Vehicle Reg No. : SHA2572C Date of Accident : 12.10.2022

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: CHINA TAIPING --- SLX1860J
2. The finalized amount shall be:
- | | |
|--|-----------------------------|
| (a) Spare Parts after List discount | <u>\$491.22</u> |
| (b) Labour Charges (include advertisement stickers etc,if any) | <u>\$640.00</u> |
| Total for Part-By-Part Repair Cost | <u>\$1,131.22</u> |
| (c.) Lumpsum Repair (if applicable) | |
| Total for Lumpsum repair cost after Less: <u>20%</u> | <u> </u> |
| Final Lumpsum Repair cost | <u> </u> |

3. Estimated normal period for repairs: 2 working days.
4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
5. Thank you for your assistance.

We confirm the estimates and
finalized amountSignature : 
Name : LIM T S
Tel : 62148398
Fax : 65468156Signature : 
Name : GUO QIANG NAZ LKK
Date : 15/12/2022**For Official Use Only**

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	<u>\$7.49 /\$2.00</u>	Y		
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305532929
REGN NO : SHA2572C
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID(G4A)
DATE OF REGN : 29.04.2022
DATE/TIME IN : 12.10.2022 16:10
ACCIDENT DATE : 12.10.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0302-2713-G REAR BUMPER LWR COVER 1 654.96 25.00 491.22 ✓ CRA

SUB-TOTAL : 491.22

JOB NATURE

0000 PB PANEL BEATING-SHA2572C-TP 350.00 ✓


0001 SP SPRAYPAINT CHARGE 250.00 ✓

0002 L R/I REVERSE SENSORS 40.00 ✓

SUB-TOTAL : 640.00

TOTAL : 1,131.22

AUTHORISED : YES / NO


MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE :

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

LKK-

DATE: 13.10.2022

INSURANCE: CHINA TAIPING CP(P)

MODEL: Toyota Prius G4A

MVA: LIM T S

VEHICLE NO.: SHA2572C

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
2712	Rear Bumper X Rep	1		\$551.89
2713	Rear Bumper Lower Cover ?/CRA	1		\$654.96
2267	Rear Bumper Clips X	10	\$2.20	\$22.00
2725	Rear Bumper Reflector LH ?XSVC	1		\$55.00
SUB TOTAL				\$1,283.85
LESS 25%				\$320.96
DISCOUNTED TOTAL				\$962.89
1150	Rear Bumper Mat X NN	1		\$50.00
PARTS TOTAL				\$1,012.89
Labour Charge				
Panel Beating				\$400.00
Spray Painting Charge				\$300.00
Remove/Refix Reverse Sensor				\$120.00
TOTAL LABOUR				\$820.00
ESTIMATE TOTAL				\$1,832.89

NETT

350
250
40

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

2 Days.

P/P

\$1131.22

Can Ag

13/10

4pm

By: [Signature]	Date: [Date]
For: [Signature]	Date: [Date]
By: [Signature]	Date: [Date]
For: [Signature]	Date: [Date]
By: [Signature]	Date: [Date]
For: [Signature]	Date: [Date]
By: [Signature]	Date: [Date]
For: [Signature]	Date: [Date]
By: [Signature]	Date: [Date]
For: [Signature]	Date: [Date]