



Your Ref: 22/23/23/VC05/026949

Date: 09th Jul 2024

Our Ref: CS1/LPC24070008/Eqh3e2

M/s Lonpac Insurance Bhd

300 Beach Road

#17-04/07 The Concourse

Singapore 199555

(The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SG 5476R

INSURED VEHICLE: YP 6319L

ACCIDENT DATE: 11/01/2023

We thank you for your instruction on 26/06/2024.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SG 5476R from M/s Vicom Assessment Centre.
- b) Colour damaged vehicle photographs of SG 5476R.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SG 5476R
Make & Model	: Volvo B9TL 9.4L Auto Turbo ABS
Year of Registration	: 2017
Chassis Number	: YV3S4P920HA182462
Engine Capacity	: 9364 cc

2. We recommend that the repairs of the entire damage require about 2 (Two) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.